



**Environmental
Protection Agency**

John R. Kasich, **Governor**
Mary Taylor, **Lt. Governor**
Scott J. Nally, **Director**

October 27, 2011

**RE: BEMIS COMPANY, INC.
LARGE QUANTITY GENERATOR
OHD 004 173 415
SUMMIT COUNTY
RTC**

Mr. Mark Dembinski
Bemis Company, Inc.
1972 Akron Peninsula Road
Akron, Ohio 44313

Dear Mr. Dembinski:

Thank you for your October 21, 2011 response to Ohio EPA's September 12, 2011 partial return to compliance letter. The documentation you submitted included an engineering assessment report for the hazardous waste tank system.

My review of this documentation reveals that Bemis Company has now abated all violations discovered during the June 24, 2011 inspection, as listed below.

Letter Citation #	Rule Citation
5.	OAC Rule 3745-66-92(A), Tank System Requirements
6.	OAC Rule 3745-66-92(B), Tank System Requirements

Should you have any questions, please feel free to call me at (330) 963-1231.

Sincerely,

Tom Roth
District Representative
Division of Materials and Waste Management

TR/cl

ec: Jeff Mayhugh, DMWM, CO
Nyall McKenna, DMWM, NEDO
Natalie Oryshkewych, DMWM, NEDO

cc: Marlene Kinney, DMWM, NEDO

NOTICE:

Ohio EPA's failure to list specific deficiencies or violations in this letter does not relieve your company from having to comply with all applicable regulations