



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

November 2, 2011

Steve Studenmund
Columbus & Franklin County Metro Park District
1069 West Main Street
Columbus, OH 43081

Re: **Walnut Woods Metro Park, Franklin County
General Storm Water Permit #4GC03386*AG**

Dear Mr. Studenmund:

This letter is written in follow-up to a construction storm water inspection that I conducted at the Walnut Woods Metro Park located at 6716 Lithopolis Road, on October 28, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment and Erosion Controls:

It appeared during the inspection that construction activity is nearly complete for this site and most all disturbed areas include a large stockpile have been permanently stabilized. However, there was an area that was beginning to receive spoil from another site that needs to be stabilized. Also, erosion controls should be installed around this area. Please see attached picture.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosure

ec: Greg Sanders, DSW/CDO

GS/nsm Walnut Woods Metro Park, October 28, 2011

Walnut Woods Metro Park
Install erosion controls
Stabilize barren areas
Walnut Creek Watershed
October 28, 2011
Photo by Greg Sanders

