



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

September 30, 2011

Teri Helman
Charter Oaks Tree and Landscaping Company
7535 Worthington Galena Road
Worthington, OH 43085

**Re: Storm Water Inspection at Charter Oaks Tree and Landscaping
Franklin County
Permit # 4GR00525*DG**

Dear Ms. Helman:

This letter is written in follow up to an industrial storm water inspection I conducted at Charter Oaks Tree and Landscaping located at 7535 Worthington Galena Road, Worthington, Ohio 43085 on September 20, 2011. The purpose of the inspection was to evaluate your Best Management Practices (BMPs) associated with the storage piles at this site.

I understand that a containment berm is currently utilized for the containment for all mulch storage associated with this site. Integrity of the berm is well-maintained and appeared functional during my inspection. Please continue to maintain the berm during all seasons to minimize pollution to off-site stormwater runoff.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Charter Oaks Tree and Landscaping 9-20-11

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov

