



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

September 26, 2011

Christy Buenconsejo  
Creative Housing Inc.  
2233 Citygate Drive  
Columbus, OH 43219

**Re: Creative Housing XIII, Franklin County**

Dear Ms. Buenconsejo:

This letter is written in follow-up to a construction storm water inspection that I conducted at the Creative Housing XIII project that is located at the end of Lamplighter Drive, in Grove City, Ohio. The inspection was conducted on September 16, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities.

Please install a concrete wash-out pit. Concrete wash-out was noted being discharged on to the ground without controls. Please see attached picture.

Please maintain erosion controls around the perimeter of the site. I noted a few sections of silt fence that needed repaired.

Please install erosion controls to prevent mud from being tracked on to Lamplighter Drive. Please see attached picture.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.


Sincerely,

Gregory L. Sanders  
Environmental Specialist  
Division of Surface Water  
Central District Office


Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO  
ec: Greg Sanders

GS/nsm Creative Housing XIII, September 16, 2011



**Creative Housing XIII**  
**Install concrete wash-out pit**  
**Scioto River Watershed**  
**September 16, 2011**  
**Photo by: Greg Sanders**



**Creative Housing XIII**  
**Sediment on road**  
**Scioto River Watershed**  
**September 16, 2011**  
**Photo by: Greg Sanders**

