



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

September 22, 2011

Franz A. Geiger
8800 Lyra Drive Suite 550
Columbus, OH 43240

**Re: Storm Water Inspection at Zumstein Property North and South
Franklin County
Permit #4GC03539*AG**

Dear Mr. Geiger:

This letter is written in follow-up to a construction storm water inspection I conducted at Zumstein Property North and South located south of Polaris Parkway, Westerville, Ohio 43082 on August 24, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment and Erosion Controls

- The sediment basin, as requested in my previous inspection report, has been installed. The basin appears to be installed and functioning as intended.

Barren Areas: 21 Day Rule

- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Zumstein Property North and South 8-24-2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728.3778
614 | 728.3898 (fax)
www.epa.ohio.gov

