



**Environmental  
Protection Agency**

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Korteski, Director



\*1PY0000220110825\*

CHAMPAIGN VALLEY VIEW MHP

REYNOLDS, JOSEP 2011/08/25



**Environmental  
Protection Agency**

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

August 25, 2011

Mr. William Neer  
Valleyview Mobile Home Park  
990 E. Hickory Grove Road  
Urbana, Ohio 43078

**RE: NOTICE OF VIOLATION AND RECONNAISSANCE INSPECTION, VALLEYVIEW  
MHP.**

Dear Mr. Neer:

On August 23, 2011 I conducted a Reconnaissance Inspection at the Valleyview MHP waste water treatment plant, 110 East Hickory Grove Road. The inspection was conducted as part of the compliance review for the facility.

There is several outstanding compliance issues associated with the waste water system at the park. These violations are significant enough that this office has deemed it necessary to recommend a formal enforcement action to correct the violations. We have scheduled a meeting with you on September 8, 2011 (10:00 AM). The meeting will be held at the Ohio EPA, Southwest District Office, 401 E. Fifth Street, Dayton, Ohio. We look forward to meeting with you and discussing the issues further on the eighth.


In the interim Electronic Discharge Monitoring Reports must be submitted on a monthly basis, in accordance with the requirements of your expired National Pollutant Discharge Elimination System (NPDES) permit. An NPDES permit renewal application and renewal fee must be submitted to this office (see attached). Finally, the waste water treatment plant must be placed under the supervision of a Class I certified waste water operator (see attached Operator of Record form). The NPDES renewal application and Operator of Record form must be completed and returned to the Ohio EPA, Southwest District Office in Dayton, by no later than September 15, 2011.

The inspection report is attached for your review. If you have any questions regarding the report, please feel free to contact me at (937) 285 - 6097.

Sincerely,

Joseph Reynolds  
Division of Surface Water

cc: Champaign County Health Department  
Pete Simcic, OEPA, Legal, CO





State of Ohio Environmental Protection Agency  
Southwest District Office

NPDES Compliance Inspection Report


Section A: National Data System Coding					
Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1PY00002*AD	OH013378Z	8/23/2011	R	S	1

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Valleyview Mobile Home Park 110 East Hickory Grove Road Urbana, Ohio 43078	10:40 AM	6/1/2003
	Exit Time	Permit Expiration Date
	10:55 AM	5/31/2008
Name(s) and Title(s) of On-Site Representatives		Phone Number(s)
None Present		
Name, Address and Title of Responsible Official		Phone Number
Mr William Neer (Owner) 990 E. Hickory Grove Road Urbana, Ohio 43078		(937) 869 - 6260 (937) 652 - 4685

Section C: Areas Evaluated During Inspection					
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)					
<input type="checkbox"/> U	Permit	<input type="checkbox"/> N	Flow Measurement	<input type="checkbox"/> N	Pretreatment
<input checked="" type="checkbox"/> U	Records/Reports	<input type="checkbox"/> N	Laboratory	<input checked="" type="checkbox"/> U	Compliance Schedule
<input type="checkbox"/> U	Operations & Maintenance	<input checked="" type="checkbox"/> U	Effluent/Receiving Waters	<input checked="" type="checkbox"/> U	Self-Monitoring Program
<input type="checkbox"/> M	Facility Site Review	<input checked="" type="checkbox"/> U	Sludge Storage/Disposal	<input type="checkbox"/> S	Other
<input type="checkbox"/> N	Collection System				

Section D: Summary of Findings (Attach additional sheets if necessary)
See attached report.

Inspector	Reviewer
<i>Joe Reynolds</i> Date: 8/25/11	
Joe Reynolds Division of Surface Water Southwest District Office	Martyn Burt Compliance & Enforcement Supervisor Division of Surface Water Southwest District Office



## Inspection Findings

An inspection of the waste water treatment plant at Valleyview Mobile Home Park was conducted on August 23, 2011. The inspection was conducted as part of the compliance review for the park.

NPDES permit number 1PY00002\*AD was issued to Valleyview Mobile Home Park on June 1, 2003. This permit expired on May 31, 2008. An NPDES permit renewal application has not been submitted. This is in violation of Ohio Revised Code, Chapter 6111.04, "Acts of Pollution Prohibited".

NPDES permit number 1PY00002\*AD contains a compliance schedule for upgrades to the treatment system designed to eliminate effluent violations. None of the compliance schedule dates have been met. These violations represent significant non-compliance of the permit. They also are violations of Ohio Revised Code Chapter 6111.04, "Acts of Pollution Prohibited".

Since December 25, 2005 Valleyview Mobile Home Park has failed to submit monthly operating report data as required by the NPDES permit. Failure to submit monthly operating reports is in violation of Ohio Revised Code Chapter 6111.04, "Acts of Pollution Prohibited".

The trash trap had caked grease behind the baffle. The cake covered and arose above the water surface in the tank.

The aeration tanks had good mixing. The blower was operating at the time of the inspection. The mixed liquor was thin. After aeration shut off the flock did not form a blanket.

The final clarifier effluent was clear. Solids were rising in the tank and carrying over to the effluent trough. There was no clear zone or visible blanket in the tank.

There is no tertiary treatment or disinfection systems currently available as part of the plants treatment train.

The treatment system discharge has not been located. The discharge reportedly goes to the field east of the park. A majority of the time the effluent pools and seeps into the ground prior to Bogles Run.

