

**Environmental
Protection Agency**

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Krieski, Director

File: Preble
Foundations
Crest Cedar Spruce
care center of
Trinity)
Sewerage

July 9, 2010

**RE: Reconnaissance Inspection (RI)
Foundations WWTP
Permit Number 1GS00003**


Vicki McDermitt
Foundations WWTP Operator
7739 US Route 40
New Paris, Ohio 47347

Dear Ms. McDermitt:

On July 1, 2010 I conducted an RI at the Foundations Wastewater Treatment Plant (WWTP). A copy of the inspection report is enclosed. The inspection report contains no marginal or unsatisfactory ratings.

If you have any questions or comments concerning the contents of this letter, please feel free to contact me at (937) 285-6103.

Sincerely,



Maureen M. Ware
Division of Surface Water

MMW/kla

cc: Preble County Health Department



State of Ohio Environmental Protection Agency
Southwest District Office

NPDES Compliance Inspection Report


Section A: National Data System Coding					
Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1GS00003	OHGS00054	07/01/2010	R	S	2

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Foundations WWTP 7739 US Route 40 New Paris, Ohio 47347	1:15 PM	3/01/2010
	Exit Time	Permit Expiration Date
	1:35 PM	12/31/2014
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Vicki McDermitt, Operator	937-437-2311	
Name, Address and Title of Responsible Official	Phone Number	
Foundations 7739 US Route 40 New Paris, Ohio 47347		

Section C: Areas Evaluated During Inspection					
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)					
N	Permit	N	Flow Measurement	N	Pretreatment
N	Records/Reports	N	Laboratory	N	Compliance Schedule
S	Operations & Maintenance	S	Effluent/Receiving Waters	N	Self-Monitoring Program
S	Facility Site Review	N	Sludge Storage/Disposal	N	Other
N	Collection System				

Section D: Summary of Findings (Attach additional sheets if necessary)

The Foundations WWTP is well operated and maintained. The effluent to the creek looks clear.

Inspector	Reviewer
 Maureen M. Ware Division of Surface Water Southwest District Office	 Martyn Burt Environmental Supervisor Division of Surface Water Southwest District Office
7/9/10 Date	7/9/10 Date