



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Garus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 726-3778 FAX: (614) 726-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

August 13, 2009

Larry Mayer
Ohio Eastern Star Home
1451 Gambier Road
Mount Vernon, OH 43050

Re: Construction Storm Water Inspection at Ohio Eastern Star Home

Dear Mr. Mayer:

This letter is written in follow-up to a construction storm water inspection Ryan Griffin and Rachelle Howe, of Ohio EPA, conducted at Ohio Eastern Star Home located at 1451 Gambier Road in Knox County on July 21, 2009. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, the following items were noted:

Sediment and Erosion Controls

- The silt fence established along the perimeter of the site appears to be functioning as intended (See Figure 1). Please ensure that all sediment controls are inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches as required by the general permit.
- It appears that the centralized sediment basin for this site is currently under construction on the northwest corner of the site (See Figure 2). This basin must be completed within 10 days from receipt of this letter.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.


Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director



Larry Mayer
Ohio Eastern Star Home
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Ohio Eastern Star Home July 21, 2009

**Ohio Eastern Star Home
Kokosing River Watershed
Photo By: Rachelle Howe
7/21/2009**



Figure 1 Established Silt Fence Along Western Perimeter

**Ohio Eastern Star Home
Kokosing River Watershed
Photo By: Rachelle Howe
7/21/2009
Sediment Basin Construction**



Figure 2 Sediment Basin Construction Located on NW Corner of Site

