



State of Ohio Environmental Protection Agency

**STREET ADDRESS:**

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

**Central District Office**

TELE: (614) 726-3778 FAX: (614) 726-3896  
www.epa.state.oh.us

**MAILING ADDRESS:**

P.O. Box 1049  
Columbus, OH 43216-1049

August 13, 2009

Tony Hudson  
Brian Wiland and Associates  
2733 West Dublin Granville Road  
Columbus, OH 43235

**Re: Storm Water Inspection at Mike Blake Residence / Franklin County  
Permit #: 4GC03051\*AG**

Dear Mr. Hudson:

This letter is written in follow-up to a construction storm water inspection by Amber Miller and Heather Nichols, of the Ohio EPA, at Mike Blake Residence located at 7920 Clark State Road on July 28, 2009. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, the following items were noted:

**Sediment and Erosion Controls:**

- Upon inspection, it appeared that the sediment and erosion controls were functioning as intended. Please be aware that the General Permit indicates that all controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on site for the agency to review.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days (See Figure 1).

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director



Tony Hudson  
Brian Wiland and Associates  
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,



Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Mike Blake Residence 7-28-09

Mike Blake Residence  
Big Walnut Creek Watershed  
Photo by: Amber Miller  
July 28, 2009



Figure 1

