

\*4GC0252220090807\*

2009/08/07

4GC02522

IGLESIA FUENTE DE SALVACION



State of Ohio Environmental Protection Agency

REET ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049  
Columbus, OH 43216-1049

August 7, 2009

Robert del M. Castillo  
Fuente de Salvacion  
445 North Greener Avenue  
Columbus, OH 43228

**Re: Storm Water Inspection at Iglesia Fuente de Salvacion / Franklin County  
Permit #: 4GC02522\*AG**

Dear Mr. Castillo:

This letter is written in follow-up to a construction storm water inspection by Amber Miller and Katie Anderson, of the Ohio EPA, at Iglesia Fuente de Salvacion located at 3631 Bexvie Avenue on July 22, 2009. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, the following items were noted:

**Sediment and Erosion Controls:**

- Upon inspection, current perimeter silt fence has failed and will require repair (See Figure 1). In particular, silt fence along Bexvie Avenue in the northeast corner of the site must be maintained.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Iglesia Fuente de Salvation 7-22-09

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director






Figure 1: Failed silt fence

