



\*4GC0323420101005\*

2010/10/05

4GC03234

HOCKING RIVER WETLAND AND STREAM  
RESTORATION



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898  
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049  
Columbus, OH 43216-1049

October 6, 2010

Denise Crews P.E.  
City of Lancaster, Ohio  
121 East Chestnut Street  
Lancaster, OH 43130

**Re: Construction Storm Water Inspection at Hocking River Wetland and Stream  
Restoration / Fairfield County  
Permit Number 4GC03234\*AG**

Dear Ms. Crews:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley of Ohio EPA at the Hocking River Wetland and Stream Restoration located south of River Valley Mall and west of Pierce Avenue on August 24, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

**Sediment and Erosion Control:**

- During the site investigation, it was found that a keyway cut was installed in the side of the retaining wall separating the drainage valley from the Hocking River (Figure 1). The lack of controls on the keyway cut are not acceptable under the General Storm Water Permit Associated with Construction Activities. The addition of a check dam or series of check dams are expected to ensure the sediment laden discharges are minimized.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at: [harry.kallipollitis@epa.state.oh.us](mailto:harry.kallipollitis@epa.state.oh.us).

Sincerely,

Harry Kallipollitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Hocking River Wetland and Stream Restoration 9-16-10

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director






Figure 1: Keyway dewatering into Hocking River

