



4GC0261420091026

2009/10/26

4GC02614

PRIMROSE SCHOOL



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

October 26, 2009

Gray Greiner
Primrose School Franchising Co.
3660 Cedarcrest Road
Acworth, GA 30101

Re: Primrose School / Franklin County

Dear Mr. Greiner:

This letter is written in follow-up to a construction storm water inspection that I conducted at the Primrose School located along Lamplighter Drive east of Buckeye Parkway in Grove City, Ohio on October 20, 2009. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:


- The perimeter silt fence will require maintenance.
- Please be aware that the General Permit indicates that all sediment controls will be inspected and maintained every seven days or after a significant rain event. A log of inspection must be maintained on site for the agency to review.
- The dumpster that was stored at the end of Lamplighter Drive was leaking and needs to be repaired or replaced. Please see attached picture.
- Please be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. Please see attached pictures.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Gray Greiner
Primrose School Franchising Co.
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.


Sincerely,



Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

GS/nsm Primrose School, October 20, 2009



Primrose School
Stabilize barren areas
Scioto River Watershed
October 20, 2009
Photo by: Greg Sanders



Primrose School
Scioto River Watershed
October 20, 2009
Photo by: Greg Sanders



Primrose School
Repair leaking dumpster
Scioto River Watershed
October 20, 2009
Photo by: Greg Sanders



