

Jim Herd
Fairfield Union Local School District
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,




Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosure


c: Jeff Bohne, Water Quality Supervisor, DSW/CDO
Jonathan I. Ferbrache, Fairfield Soil and Water Conservation District
Kevin Mohler, Bovis Lend Lease


GS/nsm Fairfield Union HS, June 9, 2011

Fairfield Union MS
Install erosion controls
Stabilize barren areas & ditch
Rush Creek Watershed
June 9, 2011
Photo by: Greg Sanders




Fairfield Union MS
Install erosion controls
Stabilize barren areas
Rush Creek Watershed
June 9, 2011
Photo by: Greg Sanders








Fairfield Union MS
Install erosion controls
Stabilize barren areas & ditch
Rush Creek Watershed
June 9, 2011
Photo by Greg Sanders




Fairfield Union MS
Maintain erosion controls
Remove sediment from road
Rush Creek Watershed
June 9, 2011
Photo by Greg Sanders







Fairfield Union MS
Stabilize barren areas
Maintain erosion controls
Rush Creek Watershed
June 9, 2011
Photo by: Greg Sanders



Fairfield Union MS
Stabilize barren areas
Install erosion controls
Rush Creek Watershed
June 9, 2011
Photo by: Greg Sanders

11-11-11





4GC0305320110620

2011/06/20

4GC03053

FAIRFIELD UNION MIDDLE SCHOOL & US RT 22
WIDENING



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 20, 2011

Bradley Rucker
National Contracting Group, LTD
690 Lakeview Plaza Blvd., Suite F
Worthington, OH 43085

Re: Coughlin Automotive - Circleville, Pickaway County

Dear Mr. Rucker:

This letter is written regarding the storm water inspection that I conducted at Coughlin Automotive located at 24001 US Route 23 South, in Circleville, Ohio. The inspection was conducted on June 14, 2011. I understand that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on my site inspection and the General Storm Water Permit, the following items must be addressed.

Sediment and Erosion Controls:

1. Most of the site was stabilized and construction appeared to be completed. However, there are several areas that will need to be re-seeded. There is a lot of sediment discharging to the storm water drains. There are rills and gullies forming which further allow the site to erode. Please re-seed and stabilize barren areas. Please see attached pictures.

If you have any questions regarding this letter or my inspection, please do not hesitate call me at our Central District Office at (614) 728-3851. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office


Enclosure

c: Jeff Bohne, CDO/DSW

GS/nsm Coughlin Automotive-Circleville, June 14, 2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov



Coughlin Automotive - Circleville
Sediment discharge to SW drain
Scioto River Watershed
June 14, 2011
Photo by: Greg Sanders



Coughlin Automotive - Circleville
Rills & gullies forming
Re-seed barren areas
Scioto River Watershed
June 14, 2011
Photo by: Greg Sanders



