



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 9, 2011

Jim Herd
Fairfield Union Local School District
6401 Cincinnati-Zanesville Road
Lancaster, OH 43130

Re: Fairfield Union Middle School / Fairfield County

Dear Mr. Herd:

This letter is written in follow-up to a construction storm water inspection that I conducted at the Fairfield Union Middle School project along State Route 22. This site is located at 6401 Cincinnati-Zanesville Road near Rushville, Ohio and the inspection was conducted on April 26, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, the following items were noted:

There was an area in the rear of the school that was barren and needed to be stabilized. Also, there were no erosion controls around the barren area and the site was eroding on to the driveway. Please be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. Please see attached pictures.

Silt fence needs to be installed and maintained around the barren areas in the rear of the middle school.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.


Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO
Jonathan I. Ferbrache, Fairfield Soil and Water Conservation District
Kevin Mohler, Bovis Lend Lease

GS/nsm Fairfield Union HS, April 26, 2011



Fairfield Union MS
Stabilize barren areas
Install erosion controls
Rush Creek Watershed
April 26, 2011
Photo by: Greg Sanders



Fairfield Union MS
Stabilize barren areas
Install erosion controls
Rush Creek Watershed
April 26, 2011
Photo by: Greg Sanders



SECRET

