



**Environmental  
Protection Agency**

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

April 18, 2011

Steve Studenmund  
Columbus & Franklin County Metro Park District  
1069 West Main Street  
Columbus, OH 43081

**Re: Walnut Woods Metro Park, Franklin County  
General Storm Water Permit #4GC03386\*AG**

Dear Mr. Studenmund:

This letter is written in follow-up to a construction storm water inspection that I conducted at the Walnut Woods Metro Park located at 6716 Lithopolis Road, on April 5, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

**Sediment and Erosion Controls:**

It appeared during the inspection that construction activity is nearly complete for this site and most all disturbed areas have been permanently stabilized. However, there is a large stockpile near a pond that still needs to be stabilized. Rills and gullies are forming on the stockpile. Also, the silt fence around the stockpile is in need of repair. Please see attached pictures.


If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders  
Environmental Specialist  
Division of Surface Water  
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

GS/nsm Walnut Woods Metro Park, April 5, 2011



Walnut Woods Metro Park  
Stabilize barren areas  
Walnut Creek Watershed  
April 5, 2011  
Photo by: Greg Sanders



Walnut Woods Metro Park  
Stabilize barren areas  
Repair silt fence  
Walnut Creek Watershed  
April 5, 2011  
Photo by: Greg Sanders



