



State of Ohio Environmental Protection Agency

REET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

August 23, 2010

Jim Herd
Fairfield Union Local School District
6401 Cincinnati-Zanesville Road
Lancaster, OH 43130

**Re: Construction Storm Water Inspection at Fairfield Union Middle School and US Route 22
Widening / Fairfield County
Permit Number 4GC03053*AG**

Dear Mr. Herd:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Megan Reising of Ohio EPA at Fairfield Union Middle School and US Route 22 Widening located at 6401 Cincinnati-Zanesville Road, Lancaster, Ohio on July 29, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

Sediment and Erosion Control:

- Our staff observed an area of concrete disposal that lacked proper containment (Figure 1). If future onsite disposal is required, containment measures such as a pit impoundment is expected.
- Our staff observed several inlets which require maintenance (Figure 2). Please continue regular onsite storm water inspections to avoid uncontrolled discharges to waters of the state.


If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Fairfield Union Middle School and US RTE 22 Widening 7-29-10

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director





Fairfield Union Middle School and US Route 22
Widening
Walnut Watershed
Photo by: Stephen Riley and Megan Reising
July 29, 2010

Note: Concrete and Motor mixing area

Figure 1: Lack proper cement washout area



Fairfield Union Middle School and US Route 22
Widening
Walnut Watershed
Photo by: Stephen Riley and Megan Reising
July 29, 2010

Note: Ripped Dandy bag and inlet filled with sediment

Figure 2: Lack of controls over inlet basin

