



State of Ohio Environmental Protection Agency

STREET ADDRESS:

W. Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 19, 2010

Robert Allman
Celmark Development Group Inc.
7630 Red Bay Court
Dublin, OH 43016

**Re: Construction Storm Water Inspection at East Village / Franklin County
Permit Number 4GC03028*AG**

Dear Mr. Allman:

This letter is written in follow-up to a construction storm water inspection conducted by Elizabeth Schaller and Vinod Tajalpuram of Ohio EPA at East Village in Columbus, Ohio on July 12, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following was noted:

Sediment and Erosion Control:

- Perimeter silt fence on the west edge of the property must be maintained until final grade is achieved and the area is established with vegetation sufficient to control erosion measured by a minimum vegetation density of 70 percent.

Post Construction Requirements:

- The General Permit mandates specific water quality treatment for storm water following the completion of construction. Please be able to demonstrate your post construction requirements per the General Permit will be met. Please submit to my attention the water quality calculations demonstrating compliance. This information can be sent to my attention via a response letter, or by email.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.


Sincerely

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm East Village 7-12-10

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director






Figure 1: Silt fence must be maintained

