



State of Ohio Environmental Protection Agency

RECEIPT ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 15, 2010

Mike Bashore
Franklin County Engineers Office
970 Dublin Road
Columbus, OH 43215

Re: Construction Storm Water Inspection at Alum Creek Drive at Rohr Road Minor Lane Addition, Wide / Franklin County Permit Number 4GC03220*AG

Dear Mr. Bashore:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Elizabeth Schaller of Ohio EPA at Alum Creek Drive at Rohr Road Minor Lane Addition, Wide, Groveport, Ohio 43068 on July 6, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The silt fence on the south side of Rohr Road requires repair to ensure efficient sediment and erosion control (See figure 1).
- The storm water catch basin at the corner of Rohr Road and Alum Creek Drive requires a silt fence box structure with ample lateral supports as noted in figure 2.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.


Sincerely,


Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Alum Creek Drive at Rohr Road Minor Lane Addition, Wide

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director





Alum Creek Dr at Rohr Rd Minor Lane Addition,
Wide
Big Walnut Creek Watershed

Photo by: Elizabeth Schaller and Stephen Riley
7-6-10

Note: Sediment controls require maintenance

Figure 1: Silt fences requiring maintenance



Alum Creek Dr at Rohr Rd Minor Lane
Addition, Wide
Big Walnut Creek Watershed

Photo by: Elizabeth Schaller and Stephen Riley
7-6-10

Figure 2: Silt fence box structure

