



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

FILE COPY

May 23, 2011

Mr. William Eitel, Plant Manager  
5600 Parsons Avenue  
Lockbourne, OH 43137

**Re: Parsons Ave WTP  
NPDES Permit 4IW00018/ OH0081604  
Reconnaissance Inspection  
Franklin County**

Dear Mr. Eitel:

On May 4, 2011, a Reconnaissance Inspection was conducted at the Parsons Ave WTP. Present for the inspection were yourself representing the water treatment plant and me of the Ohio EPA, Central District Office, Division of Surface Water. The purpose of the inspection was to evaluate compliance with the terms and conditions of your NPDES permit and to evaluate the operation and maintenance of the plant.

The facility has reported discharges only during the month of January 2010 over the past five years. The discharges resulted in effluent limit violations for total suspended solids (see attached). However, the discharge was temporarily routed to a sanitary sewer to prevent additional violations. The sanitary connection is no longer in place but the facility is unlikely to have additional discharges for the foreseeable future. No additional response is necessary.

Attached is the Reconnaissance Inspection Report. There are no items which require a response. If you have any questions or comments concerning the enclosed inspection report, please contact me at (614) 728-3846 or e-mail at [cole.miller@epa.ohio.gov](mailto:cole.miller@epa.ohio.gov).

Sincerely,

Cole Miller  
Environmental Specialist  
Field Operations Unit  
Division of Surface Water  
Central District Office

Enclosure

CM/nsm 5-4-11 Parsons Ave. WTP Recon3

NPDES Compliance Inspection Report

SECTION A: NATIONAL DATA SYSTEM CODING				
Permit #	NPDES #	Inspection Type	Inspector	Facility Type
4IW00018	OH0081604	RI	S	1
Inspection Date	Entry Time	Exit Time	Notice of Violation	SNC List
5/4/2011	1:05 PM	1:45 PM	No	No

SECTION B: FACILITY DATA	
Name and Location of Facility Inspected	Permit Effective Date
Columbus Parsons Ave WTP 5600 Parsons Avenue Lockbourne, Ohio 43137	6/1/2010
	Permit Expiration Date
	5/31/2015
Name(s) and Title(s) of On-Site Representatives	Phone Numbers
Bill Eitel, Plant Manager	(614) 645-3227
Name and Title of Responsible Official	Phone Number
Bill Eitel, Plant Manager 5600 Parsons Avenue Lockbourne, Ohio 43137	(614) 645-3227

SECTION C: AREAS EVALUATED DURING INSPECTION		
Key: S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated		
S	Compliance	
S	Operations & Maintenance	
S	Facility Site Review	
N	Collection System	
S	Flow Measurement	
S	Receiving Waters	The outfall location has been changed.
N	Laboratory	
S	Self-Monitoring Program	

Comments: The outfall was rerouted approximately 30 feet from the previous location in order to prevent erosion of the bank.

Signatures			
	5/23/11		5/23/11
Cole Miller, Inspector Compliance & Enforcement Division of Surface Water Central District Office	Date	Erin Sherer, Reviewer Compliance & Enforcement Supervisor Division of Surface Water Central District Office	Date

## Compliance Data for Parsons Ave WTP between 2/1/2006 to 4/1/2011

### Summary

Permit Effluent Limit Violations: 3

Permit Effluent Code Violations: 0

Permit Effluent Frequency Violations: 0

Limit Violations						
Reporting Period	Station	Parameter	Limit Type	Limit	Reported Value	Violation Date
January 2010	001	Total Suspended Solids	30D Conc	30	106.5	1/1/2010
January 2010	001	Total Suspended Solids	1D Conc	45	73.	1/13/2010
January 2010	001	Total Suspended Solids	1D Conc	45	140.	1/26/2010