



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Lazarus Government Center  
50 W. Town St., Suite 700  
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 726-3898  
www.epa.state.oh.us

P.O. Box 1049  
Columbus, OH 43216-1049

May 1, 2009

Mr. David C. Ruff  
Maintenance Director  
St. Johns Evangelical Lutheran Church & School  
12809 State Route 736  
Marysville, OH 43040

**Re: 4PT00006/OH0102008**  
**St. Johns Evangelical Lutheran Church & School**  
**Union County**

Dear Mr. Ruff:

This inspection was conducted on April 22, 2009 by Ohio EPA personnel. At the time of the inspection the facility was marginally satisfactory.

As discussed on site, the trashtraps need pumped, at a minimum of every six months. In addition the return sludge pipe needs replaced. As requested, please use this link to take advantage of free operation training,

<http://www.epa.state.oh.us/dsw/opcert/opcert.html>

If you have any questions, comments or concerns, please call me at (614) 728-3847.

Sincerely,

Sherree Gossett-Johnson  
Environmental Specialist II  
Compliance/Enforcement Section  
Division of Surface Water

SGJ/nsm St. Johns Union County 2009

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

**NPDES COMPLIANCE INSPECTION REPORT**

**Section A: National Data System Coding**

<b>Permit #</b> 4PT00006	<b>NPDES</b> OH0131016	<b>Mo/Day/Yr</b> 4/22/2009	<b>Insp. Type</b> R	<b>Inspector</b> S	<b>Fac Type</b> 1
-----------------------------	---------------------------	-------------------------------	------------------------	-----------------------	----------------------

**Section B: Facility Data**

**Facility Name:** St. Johns School  
**Address:** 16561 Kedall  
**City/State/Zip:** Marysville, Ohio

<b>Entry Time</b> ^1:00:00 PM	<b>Permit Eff. Date</b> 12/1/2008
<b>Exit Time</b> ^2:00:00 PM	<b>Permit Exp. Date</b> 11/30/2013

**Operator**  
**Name:** David Ruff  
**Title:** Operator  
**Phone:** 937 644-5540

**Responsible Official**  
**Name/Title:** Rusty Baldin  
**Address:** Same as above  
**Phone:** 740 417-3646

**Section C: Areas Evaluated During Inspection:**

(S=Satisfactory, M=Marginal, U=Unsatisfactory, NA = Not Applicable, N=Not-Evaluated)

Permit	S	Effluent/ Recieving Waters	S
Records/Reports	S	Sludge Storage/ Disposal	S
Operations & Maintenance	S	Pretreatment	N/A
Facility Site Review	M	Compliance Schedules	N/A
Collection System	N	Self-Monitoring Program	N/A
Flow Measurement	S	Other	N/A
Laboratory	N/A		

**Section D: Summary of Findings/Comments:**

As discussed on site, the trash traps need to be pumped at least every 6 months. In addition, the return line needs to be replaced.

Name of Inspector: Sheree Gossett-Johnson

Ohio EPA, Central District Office

Signature: 

Date: 4/27/09

Name of Reviewer: Erin Sherer

Ohio EPA, Central District Office

Signature: 

Date: 4/28/09