



State of Ohio Environmental Protection Agency

Central District Office

REET ADDRESS:

MAILING ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

July 22, 2009

John Keller
ODRC
868 Freeway Drive North
Columbus, OH 43229

**Re: Storm Water Inspection at Segregation Housing and Medical Facility Replacement
Phase II Building Construction/Permit #4GCD00031*AG**

Dear Mr. Keller:

This letter is written in follow-up to a construction storm water inspection by Katie Anderson and Rachelle Howe, of the Ohio EPA, at Segregation Housing and Medical Facility Replacement located at 11781 State Route 762 in Pickaway County on July 8, 2009. The purpose of the inspection was to ensure continued compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:

- It appeared that the silt fence on site is buried (See Photo Figure 1). The silt fence must be re-installed to ensure proper functioning.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven days.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.


Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/mjs Segregation and Med Fac. Replacement pm2 July 8, 2009

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director





Segregation Housing & Medical Facility
Replacement, Ph 2
Big Darby Creek Watershed
photo by: Kaire Anderson
July 8, 2009

Figure 1: buried silt fence

10

