

Mr. Cooper and Mr. Campbell
Master Church Builders
Page -2-

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851 or email at greg.sanders@epa.state.oh.us.

Sincerely,



Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

Enclosure


c: jeff Bohne, Water Quality Supervisor, DSW/CDO


GS/nsm Crossroads Christian Church, March 23, 2011

Crossroads Christian Church
Stabilize barren areas
Repair silt fence
Paint Creek Watershed
March 23, 2011
Photo by: Greg Sanders




Crossroads Christian Church
Stabilize barren areas
Repair silt fence
Paint Creek Watershed
March 23, 2011
Photo by: Greg Sanders





Crossroads Christian Church
Stabilize barren areas
Paint Creek Watershed
March 23, 2011
Photo by: Greg Sanders



Crossroads Christian Church
Stabilize barren areas
Paint Creek Watershed
March 23, 2011
Photo by: Greg Sanders

