



\*4GC0346820110809\*

2011/08/09

4GC03468

NEW ALBANY CARE CENTER



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

August 9, 2011

Paul Schmitt  
Terra Valley Excavating  
PO Box 325  
Bellville, OH 44813

**Re: Construction Storm Water Inspection at New Albany Care Center  
Franklin County  
Permit Number: 4GC03468 \*AG**

Dear Mr. Schmitt:

This letter is written regarding a storm water inspection conducted by Greg Mann and Daelann Farnlacher of the Ohio EPA at New Albany Care Center located at 5691 Thompson Road Columbus Ohio on July 18, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Our staff noted a storm water outfall installed to drain water from the site. At this time erosion control was properly maintained below the outfall (see Figure 1)
- Please ensure that all offsite drainage is routed through the outfall and is not escaping through perimeter barriers fence to minimize offsite sediment transport.
- Please ensure all inlet protections are installed, specifically the inlet noted in Figure 2 are properly protected from sediment runoff.

**Post Construction Requirements:**


The General Storm Water Permit requires specific post construction water quality treatment for all sites. Guidance regarding the post construction requirements is found at:

<http://www.epa.state.oh.us/dsw/storm/CGPPCQA.aspx>. Please submit to my attention (email preferred at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us)) which practice will be installed at this site to ensure compliance with the General Permit. Please include all design criteria and calculations in your submission.

Paul Schmitt  
Terra Valley Excavating  
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,



Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm New Albany Care Center 7-18-11

New Albany Care Center located at 5691  
Photo Taken By Daelann Farnlacher  
Big Walnut Watershed

Centralized Sediment Outfall



Figure 1



New Albany Care Center located at 5691

Photo Taken By Daelann Farnlacher  
Big Walnut Watershed

Un-protected Storm Water Inlet

Figure 2

