



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 4, 2011

Michael Murphy
Murphy Development Company
4393 Arbor Lake Drive
Groveport, OH 43125

Re: Cobbleton Grove Condominiums / Franklin County

Dear Mr. Murphy:

This letter is written regarding the storm water inspection that I conducted at Cobbleton Grove Condominiums, located along Ebright Road, in Franklin County, on July 28, 2011. I understand that these construction activities are covered under the General Storm Water Permit Associated with Construction Activities. Based on my site inspection and the General Storm Water Permit, the following items must be addressed:

Sediment and Erosion Controls:

There appeared to be construction activity at the site. Sediment was discharging on to the streets and to the storm water drains. Straw waddles and/or silt fence is needed around the barren areas to prevent run-off. Dandy bags need to be installed and maintained on the storm water drains. Please see attached pictures.


Please be aware that the General Permit mandates that all barren areas which remain idle areas in excess of 21 days be protected from erosion (i.e., seed and straw), within seven days from the last construction activity.

If you have any questions regarding this letter or my inspection, please do not hesitate to call me at our Central District Office at (614) 728-3851.


Sincerely,

Gregory L. Sanders
Storm Water Unit
Division of Surface Water
Central District Office

GS/nsm Cobbleton Grove Condos, July 28, 2011



Cobbleton Grove Condos
Install & maintain erosion controls
Sediment on streets
Blacklick Creek Watershed
July 28, 2011
Photo by Greg Sanders



Cobbleton Grove Condos
Install & maintain erosion controls
Sediment on streets
Blacklick Creek Watershed
July 28, 2011
Photo by Greg Sanders



