



4GC0354220110726

2011/07/26

4GC03542

WESTERVILLE NORTH HIGH SCHOOL STADIUM



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 26, 2011

Jeff Lerosé
Westerville City Schools
936 Eastwind Drive
Westerville, OH 43081

**Re: Construction Storm Water Inspection at Westerville North High School Stadium
Delaware County
Permit Number: 4GC03542 *AG**

Dear Mr. Lerosé:

This letter is written regarding a storm water inspection conducted by Greg Mann and Lindsey Boaz of the Ohio EPA at Westerville North High School Stadium located at 950 County Line Road Westerville Ohio on July 11, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:


- Sediment controls for this project must be implemented in accordance with the General Storm Water Permit. Silt fencing must be implemented along the contour and control areas where sheet flow is present. The silt fence must be trenched in otherwise proper reinstallation will be required. Sediment traps must be utilized for areas of concentrated flow specifically as noted in **Figure 1**.
- All traps must be sized in accordance with the permit requirements.
- During our inspection our staff noted apparent uncontrolled barren areas draining to structures that are not intended for sediment control. Please include appropriate storm water control methods (sediment traps) to minimize off-site sedimentation turbidity from the site (see Figure 1).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO



Westerville North High School Stadium
Big Walnut Watershed
Photo taken by Greg Mann

Improper Drainage



Figure 1

