



4GC0163320110720

2011/07/20

4GC01633

EAST LANDINGS SECTION 1 PARTS 1 & 2



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 20, 2011

Rich Conie
Maronda Homes, Inc.
3811 Twin Creeks Drive
Columbus, OH 43204

Re: East Landings Section 1, Parts 1 & 2 / Franklin County

Dear Mr. Conie:

This letter is written in follow-up to a construction storm water inspection that I conducted at the East Landings, Sec. 1, Parts 1 & 2, located in the northwest corner of the intersection of Refugee Road and Hamilton Road on July 5, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following:

Sediment Controls and Maintenance:

- Upon inspection, there was one barren home lot and the lot did not have adequate erosion controls. Please have silt fence or straw wattles placed around the perimeter of the lot and stabilize the barren areas. Please see attached pictures.
- The concrete wash pit was in need of repair. Please repair the concrete wash pit immediately. Please see attached picture.
- Maintenance of Controls: The sediment controls implemented on this site, including the concrete washout, will require maintenance or reinstallation to ensure a proper functioning condition. This general permit states that all sediment controls will be inspected and maintained every seven days or within 24 hours of a precipitation event equal to or greater than 0.5 inches. A log of inspection must be maintained on site for the agency to review. The log that was on-site was not up-to-date.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,


Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

GS/nsm East Landing, Sec. 1, July 5, 2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov



East Landings, Sec. 1, Pts. 1 & 2
Install erosion controls
Stabilize barren areas
Big Walnut Creek Watershed
July 5, 2011
Photo by: Greg Sanders



East Landings, Sec. 1, Pts. 1 & 2
Maintain concrete wash-out pit
Big Walnut Creek Watershed
July 5, 2011
Photo by: Greg Sanders



