



\*4GCO000320110711\*

2011/07/11

4GCO0003

DELAWARE AREA CAREER CENTER



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 11, 2011

Christopher Bell  
4565 Columbus Pike (US Route 23)  
Delaware OH 43015

**Re: Construction Storm Water Inspection at Delaware Area Career Center  
Delaware County  
Permit Number: 4GCO00039\*AG**

Dear Mr. Bell:

This letter is written regarding a storm water inspection conducted by Greg Mann and Daelann Farnlacher of the Ohio EPA at Delaware Area Career on June 22, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Our staff noted the dewatering activities appear properly managed at the time of the inspection. Please ensure all future dewatering activities do not result in turbid discharges into waters of the state (see Figure 2).
- On the southwest side of the sediment basin, our staff noted the perimeter barrier silt fence is not properly entrenched. Silt fence must be buried four to six inches in the ground to minimize sediment runoff into waters of the state. Please perform appropriate maintenance to ensure the effectiveness of perimeter barriers (see Figure 1).

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office


Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Delaware Area Career Center 6-22-2011

Central District Office  
50 West Town Street, Suite 700  
P.O. Box 1049  
Columbus, OH 43216-1049


614 | 728 3778  
614 | 728 3898 (fax)  
[www.epa.ohio.gov](http://www.epa.ohio.gov)





Delaware Area Career Center  
Olanchoy, Maryland  
Photo by: Stephen Frayhauser  
6/22/11  
Lundborg, sediment trap

Figure 1



Delaware Area Career Center  
Olanchoy, Maryland  
Photo by: Stephen Frayhauser  
6/22/11  
Lundborg, sediment trap

Figure 2

