



## REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

September 11, 2008

### Certified Mail

Missy Stanaway  
Speedway SuperAmerica LLC  
P.O. Box 1500  
Springfield, OH 45504

RE: Ohio EPA Facility ID 0855010466  
SSA #6348 – 120 N. Miami Ave, Bradford, OH 45308  
Failure to Pass Air to Liquid Ratio Test

Dear Ms. Stanaway:

### WARNING LETTER

On July 31, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Speedway SuperAmerica LLC #6348 (SSA #6348) located at 120 North Miami Avenue in Bradford, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #6348 revealed violations of state and local air pollution control regulations.

SSA #6348 did show compliance through the completion of a successful static leak test on July 31, 2008, however, this site failed to show compliance with the Air to Liquid ratio (A/L) testing requirements of CARB Executive Order G-70-164-AA on pumps #1, #2, and #3. Failing to demonstrate compliance with the A/L performance test requirements is a violation of Ohio Administrative Code (OAC) rule and Miami County Board of Health Local Air Pollution Control Regulations (MCBHLAPCR) section 3745-21-09 (DDD), OAC rule and MCBHLAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. On July 31, 2008, an Official Order was issued to SSA #6348 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no A/L retest has been scheduled with RAPCA.

Since the above noted GDF is currently operating in violation of OAC rules and MCBHLAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-

