



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

April 14, 2009

Certified Mail

Larry Board
Northridge Car Care LLC
1321 Moorefield Road
Springfield, OH 45503

**RE: Ohio EPA Facility ID 0812100573
Failure to perform annual stage II vapor recovery compliance testing**

WARNING LETTER

Dear Mr. Board:

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2), the stage II vapor control system at the Northridge Car Care LLC gasoline dispensing facility (GDF) located at 1321 Moorefield Road in Springfield, Ohio, must perform and successfully pass the testing requirements contained in OAC rule 3745-21-10. In accordance with the yearly static pressure decay testing requirements specified in CARB Executive Order G-70-150-AE and the Static Leak Test contained in OAC rule 3745-21-10, Appendix A, Static Leak testing and Air to Liquid Ratio (A/L) testing shall be successfully conducted at least once in each twelve consecutive month period after the date of successful completion of the startup or most recent Static Leak Test.

OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(1) state: "no owner or operator of a gasoline dispensing facility may cause, allow or permit the transfer of gasoline from a stationary storage tank at a GDF into a motor vehicle . . . unless the following requirements are met: . . . (c) The vapor control system has successfully passed the testing requirements contained in paragraph (DDD)(2) of this rule." This GDF is required to demonstrate compliance on an annual basis. The last stage II vapor recovery compliance test conducted at this GDF, on file with the Regional Air Pollution Control Agency (RAPCA), was on November 17, 2003. On March 3, 2009, RAPCA issued an Official Order to Northridge Car Care LLC, requiring this GDF to schedule an annual stage II vapor recovery compliance test within thirty (30) days of the issuance of the Order. To date, no testing has been scheduled with RAPCA at this site. Northridge Car Care LLC is currently operating in violation of OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2) and the prohibitions in Ohio Revised Code (ORC) section 3704.05.