



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

January 2, 2009

Certified Mail

Samir Hmidan
Salem Sunoco
3900 Salem Ave
Dayton, OH 45406

**RE: Ohio EPA Facility ID 0857731824
Failure to perform annual stage II vapor recovery compliance testing**

WARNING LETTER

Dear Mr. Hmidan:

Pursuant to Ohio Administrative Code (OAC) rule and Montgomery County Combined General Health District Air Pollution Control Regulations (MCCGHDAPCR) section 3745-21-09 (DDD)(2), the stage II vapor control system at the Salem Sunoco gasoline dispensing facility (GDF) located at 3900 Salem Avenue in Dayton, Ohio, must perform and successfully pass the testing requirements contained in OAC rule 3745-21-10. In accordance with the yearly static pressure decay testing requirements specified in CARB Executive Order G-70-153-AD and the Static Leak Test contained in OAC rule 3745-21-10, Appendix A, Static Leak testing and Air to Liquid Ratio (A/L) testing shall be successfully conducted at least once in each twelve consecutive month period after the date of successful completion of the startup or most recent Static Leak Test.


OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(1) state: "no owner or operator of a gasoline dispensing facility may cause, allow or permit the transfer of gasoline from a stationary storage tank at a GDF into a motor vehicle . . . unless the following requirements are met: . . . (c) The vapor control system has successfully passed the testing requirements contained in paragraph (DDD)(2) of this rule." This GDF is required to demonstrate compliance on an annual basis. The last successful stage II vapor recovery compliance test conducted at this GDF was on September 21, 2007. On November 7, 2008, the Regional Air Pollution Control Agency (RAPCA) issued an Official Order to Salem Sunoco, requiring this GDF to schedule an annual stage II vapor recovery compliance test within thirty (30) days of the issuance of the Order. To date, no testing has been scheduled with RAPCA at this site. Salem Sunoco is currently operating in violation of OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2) and the prohibitions in Ohio Revised Code (ORC) section 3704.05.

Salem Sunoco
January 2, 2009
Page 2

This letter serves as official notification from RAPCA to cease operation in violation of OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2) and ORC section 3704.05. It is imperative that Salem Sunoco schedule and show compliance with stage II testing requirements. **Please respond, in writing, to this notice within fourteen (14) days after receipt. The response will specify the intended test date.** Your tester should contact Lynn Thompson, at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman
Air Pollution Control Specialist

Cc: Jeff Canan RAPCA
Tom Kalman OEPA
Lisa Holscher USEPA

U.S. Postal Service TM
CERTIFIED MAIL TM RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$	
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Samir Hmidan		
§	Salem Sunoco	
§	3900 Salem Avenue	
o	Dayton, OH 45406	
z		

Brandon
Postmark Here
** NO green card even returned*

AIR POLLUTION CONTROL AGENCY
Marke, Greene, Miami, Montgomery & Preble Counties
South Main Street, Dayton, Ohio 45422-1280
7-225-4435 — Fax: 937-225-3486
www.rapca.org

January 2, 2009

PS Form 3800, August 2008 See Reverse for Instructions
Salem Sunoco
3900 Salem Ave
Dayton, OH 45406

RE: **Ohio EPA Facility ID 0857731824**
Failure to perform annual stage II vapor recovery compliance testing

WARNING LETTER

Dear Mr. Hmidan:

Pursuant to Ohio Administrative Code (OAC) rule and Montgomery County Combined General Health District Air Pollution Control Regulations (MCCGHDAPCR) section 3745-21-09 (DDD)(2), the stage II vapor control system at the Salem Sunoco gasoline dispensing facility (GDF) located at 3900 Salem Avenue in Dayton, Ohio, must perform and successfully pass the testing requirements contained in OAC rule 3745-21-10. In accordance with the yearly static pressure decay testing requirements specified in CARB Executive Order G-70-153-AD and the Static Leak Test contained in OAC rule 3745-21-10, Appendix A, Static Leak testing and Air to Liquid Ratio (A/L) testing shall be successfully conducted at least once in each twelve consecutive month period after the date of successful completion of the startup or most recent Static Leak Test.

OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(1) state: " no owner or operator of a gasoline dispensing facility may cause, allow or permit the transfer of gasoline from a stationary storage tank at a GDF into a motor vehicle . . . unless the following requirements are met: . . .

(c) The vapor control system has successfully passed the testing requirements contained in paragraph (DDD)(2) of this rule." This GDF is required to demonstrate compliance on an annual basis. The last successful stage II vapor recovery compliance test conducted at this GDF was on September 21, 2007. On November 7, 2008, the Regional Air Pollution Control Agency (RAPCA) issued an Official Order to Salem Sunoco, requiring this GDF to schedule an annual stage II vapor recovery compliance test within thirty (30) days of the issuance of the Order. To date, no testing has been scheduled with RAPCA at this site. Salem Sunoco is currently operating in violation of OAC rule and MCCGHDAPCR section 3745-21-09 (DDD)(2) and the prohibitions in Ohio Revised Code (ORC) section 3704.05.

