

**Environmental
Protection Agency**

_____, Governor
_____, Lt. Governor
_____, Director

June 24, 2010

RE: AMERICAN STANDARD INC
3GR00627*DG
STORMWATER
COLUMBIANA COUNTY

Mr. Joe Winch
American Standard, Inc
605 South Ellsworth Ave
Salem, Ohio 44460

Dear Mr. Winch:

On June 23, 2010 this writer conducted an inspection of your facility, located at 605 South Ellsworth Avenue in Salem, Ohio to determine compliance with your Industrial General Storm Water NPDES permit referenced above. Along with my observations from the inspection I have provided comments concerning your NPDES permit below:

General:

1. This site is the location of American Standard Inc, manufacturers of ~~heating and refrigeration~~ ^{porcelain + acrylic baths} equipment.
2. Drainage on the site is directed to two main outfalls, outfall 001 on the northwest portion of the property and outfall 004 on the southern portion of the property.

Inspection Observations:

1. There were small pieces of scrap metal on the ground behind the main building.
2. There was an exposed pile of wood pallets on the property.

Permit:


1. The SWPPP should be revised yearly to take into account any changes that occur to the site.
2. The site map should be updated and enlarged to clarify site drainage.

Action Items

- Sweep up scrap metal pieces.
- Move wood pallets to an enclosed area or cover them with a temporary or permanent cover.
- Update SWPPP.
- Update site map.

If you should have any questions concerning this letter, feel free to contact this writer at (330) 963-1125 or by email lindsey.olmstead@epa.state.oh.us.

Sincerely,



Lindsey A. Olmstead
Assistant to the District Engineer
Division of Surface Water

LAO/mt

Northeast District Office
2110 East Aurora Road
Twinsburg, OH 44087-1924

330 | 963 1200
330 | 487 0769 (fax)
www.epa.ohio.gov