



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

July 7, 2008

RE: MEDINA COUNTY  
BP SEVILLE BULK PLANT  
ICE OIL COMPANY  
(PERMIT NO. 3IN00296)

BP Oil Company  
ATTN: Frank Marsek  
4850 East 49<sup>th</sup> St.  
Cuyahoga Hts., OH 44125

Dear Mr. Marsek:

On June 12, 2008, a compliance inspection was conducted on the wastewater treatment works serving the BP Seville Bulk Plant (owner: Ice Oil), located at 11 Market Street, Seville, Medina County. The purpose of the inspection was to evaluate the facility's operation and maintenance condition, and compliance with your National Pollutant Discharge Elimination System (NPDES) permit to discharge.

The site is a bulk storage and truck fueling facility for petroleum products. Six bulk storage tanks are located on the property (four below ground, two above ground), from which fuel can be dispensed to smaller bulk and commercial vehicles.

The treatment facility is permitted to discharge treated storm water from the outfall of a retention pond to an unnamed tributary to Chippewa Creek.

Water consisting of rainwater, which may have incidental contact with oil products on paved areas around fuel loading, unloading, and dispensing areas, is collected in trench drains and routed through an 8000 gallon oil-water separator. From the oil-water separator, the water flows into a lined retention pond.

The outfall from the pond is capped, and discharge only occurs when the effluent pipe is manually uncapped. Treated effluent is discharged approximately 3 to 6 times per year.

At the time of the June 12 inspection, the retention pond contained standing water, and the surface of the water exhibited a visible oil sheen. No discharge was seen from the pond to the receiving ditch.

BP OIL COMPANY  
JULY 7, 2008  
PAGE 2

A review of the compliance history for this facility (for the period of December 1, 2006 through June 1, 2008), as generated by our SWIMS data management tracking system, found no numerical effluent limits violations (based upon monthly data submitted to the Ohio EPA). The compliance review did, however, indicate the following monitoring frequency violations:

<b>Violation Date</b>	<b>Station</b>	<b>Reporting Code</b>	<b>Parameter</b>	<b>Sample Frequency</b>	<b>Expected</b>	<b>Reported</b>
6/1/2007	001	00056	Flow Rate	1/Month	1	0
10/1/2007	001	00056	Flow Rate	1/Month	1	0

Please contact this office in writing, within 14 days of the receipt of this correspondence, indicating the reason why MOR data was not submitted those months. If data was collected, please enter the revised data into the SWIMS system, and forward a hard copy to this office.

If there are further questions regarding this letter, please contact this office.

Respectfully,



Charles E. Allen  
Environmental Engineer  
Division of Surface Water

CEA:bo