



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

October 10, 2007

RE: NORTH CANTON TRAVEL CENTER
3IN00205*CD
STARK COUNTY

Mr. Gary Sturgeon, Manager
North Canton Travel Center
4450 NW Portage Street
North Canton, OH 44720

Dear Mr. Sturgeon:

On September 28, 2007 this writer conducted a compliance evaluation of your outfalls for the North Canton Travel Center. At the time of the inspection it had not recently rained and there was no flow at outfalls 601, 001, and 002. The oil/water separator had a thick accumulation of floating oil on the surface of the water inside the tank. Please inform this office when the last time the oil has been removed from the separator, and if there is a regular maintenance schedule to perform this task. A review of your compliance history as identified by our SWIMS tracking system identified the following violations for the time period of October 2005 thru August 2007:

Numeric Violations

Station	Parameter	Limit Type	Limit	Reported Value	Violation Date
601	Oil and Grease, Hexane	30D Conc	15	17.	1/1/2006
601	Oil and Grease, Hexane	1D Conc	20	62.	6/5/2007
601	Oil and Grease, Hexane	30D Conc	15	62.	6/1/2007

Frequency Violations

Violation Date	Station	Parameter	Sample Frequency	Expected	Reported
2/1/2006	601	pH	1/Month	1	0
2/1/2006	601	Oil and Grease, Hexane	1/Month	1	0

Our files do not include the non-compliance notifications that are required as outlined in Part III, Section 12 of the NPDES permit. This is a separate violation of your permit for each event. Please be advised that violations of your NPDES permit may subject you to a possible enforcement action to be initiated by this office in accordance with Ohio Revised Code 6111.

If you should have any questions, feel free to contact this writer at (330) 963-1136.

Sincerely,

Philip P. Rhodes, P.E.
Environmental Engineer
Division of Surface Water

PPR/mt

File: Industrial Permit/Compliance

North Canyon Trave 8/28/2007 view
of separator in ground

