



**Environmental  
Protection Agency**

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 18, 2011

RE: SUN PIPELINE CO.  
HUDSON PUMP STATION  
3IG00086\*BD  
SUMMIT COUNTY

Ms. Monica Styles, HES Coordinator  
Sunoco Partners Marketing Terminal L.P.  
7155 Inkster Road  
Taylor, Ohio 48180

Dear Ms. Styles:

On July 12, 2011, this writer conducted a compliance evaluation inspection of the above referenced facility. This facility is a bulk storage and transfer facility for petroleum products. Three storage tanks are located within one large dike. Stormwater is collected within this dike and periodically discharged to the East to a rock lined swale leading to a small pond. This pond overflows to an unnamed tributary of Fishcreek.

At the time of my inspection the following observations were made:

- 1) There was stormwater accumulated in the eastern tank farm dike.
- 2) There was no discharge at the time of the inspection. There were no visual problems noted with the discharge channel or the small pond downstream.

A review of the compliance history (as generated by our computer tracking system) revealed the following violation of the NPDES Permit for the time period beginning September 2008 through May 2011:

Numeric Violation

Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
001	00550	Oil and Grease, Total	1D Conc	20	26.	6/2/2009

If you should have any questions concerning any of the above feel free to contact this writer at (330) 963-1136 or by e-mail at [phil.rhodes@epa.state.oh.us](mailto:phil.rhodes@epa.state.oh.us).

Sincerely,

Philip P. Rhodes, P.E.  
Environmental Specialist II  
Division of Surface Water

PPR/mt

File: Industrial Permit/Compliance