



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

February 26, 2009

RE: SUMMIT COUNTY  
MELODY VILLAGE WWTP #10  
OHIO EPA #3PG00021\*HD  
COMPLIANCE EVALUATION INSPECTION

Mr. David E. Marquard  
Summit County, Environmental Services  
2525 State Road  
Cuyahoga Falls, OH 44223

Dear Mr. Marquard:

On February 25, 2009, this office conducted a Compliance Evaluation Inspection at the above referenced wastewater treatment plant. The 160,000 gpd plant consists of grit removal, a comminutor, extended aeration, final clarifiers, ultraviolet disinfection, and aerobic digestion.

At the time of the inspection, the plant appeared to be in good condition. All components of the treatment plant appeared to be operating properly, with the exception of a broken comminutor. The plant's effluent appeared to be clear of visible solids.

Upon review of your Discharge Monitoring Reports (DMRs) from January 2007 through January 2009, the following numeric effluent violation was noted:

Reporting Period	Parameter	Limit Type	Limit	Reported Value	Violation Date
April 2007	Dissolved Oxygen	1D Conc	5.0	3.	4/23/2007

If you have any questions or concerns, please contact this office at (330) 963-1151.

Sincerely,

Jennifer S. Bennage  
Environmental Engineer  
Division of Surface Water

JSB/mt

cc: Bob Hollis, Summit County D.O.E.S.