



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

Re: Marion County
Whirlpool – Marion
NPDES Permit

June 29, 2011

Ms. Mary Jakeway
Whirlpool Corporation – Marion Division
1300 Marion-Agosta Road
Marion, Ohio 43301

Dear Ms. Jakeway:

This will acknowledge our June 21, 2011, compliance inspection at your Marion facility. This facility is located at 1300 Marion-Agosta Road. This inspection was conducted as part of the facility's NPDES permit No. 2IC00009. This inspection also included a brief tour of the manufacturing plant and outdoor areas.

At the time of the inspection, there was a small clear discharge at Outfall 002. When a discharge occurs, it must be sampled in accordance with your NPDES permit. On May 21, 2011, coverage under the general permit for stormwater was approved (2GR01665*DG). We are in the process of revoking your existing NPDES permit that will expire on September 30, 2011.

Our cursory review of your Discharge Monitoring Reports (4/2009 – 6/2011) for the Marion facility indicated two effluent violations. Please refer to the enclosed violation table. A completed inspection report is included for your review. If you have any questions or comments, please call me at 419-373-3021.

Sincerely,

Jason Ko
Division of Surface Water

/cs

Enclosures

pc: ~~DSW~~, ~~NWDO~~ File

NPDES COMPLIANCE INSPECTION REPORT

Section A: National Data System Coding

Permit #	NPDES	Yr/Mo/Day	Inspection Type	Inspector	FacType
21C00009	OH0007358	2011/6/21	C	S	I

Section B: Facility Data

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Whirlpool Corporation – Marion Division 1300 Marion-Agosta Road Marion, OH 43301	10:00 A.M.	10/1/2006
	Exit Time	Permit Expiration Date
	11:00 A.M.	9/30/2011

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Ms. Mary Jakeway	(740) 383-7607

Name, Address and Title of Responsible Official	Phone Number
Ms. Mary Jakeway Whirlpool Corporation – Marion Division 1300 Marion-Agosta Road Marion, OH 43301	(740) 383-7607

Section C: Areas Evaluated During Inspection


(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>--</u> Pretreatment
<u>N</u> Records/Reports	<u>--</u> Laboratory	<u>--</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluents	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>--</u> Sludge Storage/Disposal	<u>-</u> Other

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

- * Small clear discharge was noted at Outfall 002 (rained the day before)
- * Approved for stormwater general permit coverage (2GR01665*DG) on 5/25/2011
- * Currently in process of decommissioning 7 outdoor fuel storage tanks
- * A review of Discharge Monitoring Reports (4/2009 – 6/2011) indicated two effluent violations


6/25/11
 Name(s) and Signature(s) of Inspector(s) _____ Date _____, Ohio EPA, Northwest
District Office


 Name and Signature of Reviewer _____ Date 6/24/11, Ohio EPA, Northwest
District Office

Get New Data

Permit No	Reporting Period	Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
2IC00009*ID	April 2009	002	00400	pH	1D Conc	6.5	6.09	4/14/2009
2IC00009*ID	May 2011	002	00552	Oil and Grease, Hexane	1D Conc	10	17.	5/31/2011