



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 5, 2011

RE: CUYAHOGA COUNTY
CITY OF ROCKY RIVER
JOE'S DELI
NPDES PERMIT NO. OHC000003
OHIO EPA PERMIT NO. 3GC05396*AG
CONSTRUCTION STORM WATER

Mr. Joe Kanaan
Joe's Deli
19215 Hilliard Blvd.
Rocky River, OH 44116

Dear Mr. Kanaan:

On June 21, 2011, Ohio EPA conducted an inspection of the Joe's Deli project located at 19215 Hilliard Blvd., City of Rocky River, Cuyahoga County. Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC05396*AG. I spoke with Jeff Toghil, Project Superintendent of Fortney & Weygandt Inc. while on site. The inspection documented the following:

- The silt fence near the entrance of the construction site has fallen over. Please repair or replace silt fence as necessary with the specifications detailed in the Storm Water Pollution Prevention Plan (SWP3) (See Figure 1).
- The construction entrance is inadequate, resulting in offsite tracking of sediment. Please refer to the **Ohio Rainwater and Land Development Manual** (attached) and reconstruct the entrance accordingly (See Figure 2).
- There are no sediment control measures on site near the Hilliard Blvd. intersection. The SWP3 details a silt fence along the perimeter of the site near the intersection but none was present. Please be sure to install silt fence with the specifications detailed in the SWP3 (See Figures 3&4).

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Also, please fax a copy of your most recent storm water inspection report to my attention at (330) 487-0769 or via e-mail at timothy.mcparland@epa.state.oh.us. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,

Tim McParland
Assistant to the District Engineer
Division of Surface Water

TM/mt

cc: Kevin Beirnes, Building Department, City of Rocky River
Pamela Bobst, City of Rocky River, Mayor
Cuyahoga SWCD

ec: Jeff Toghil, Project Superintendent
Dan Bogoevski, Ohio EPA, NEDO, DSW



Figure 1. The silt fence needs to be maintained.



Figure 2. The construction entrance is inadequate.



Figure 3. No sediment control measures visible near the intersection.




Figure 4: No sediment controls in place except a collapsed silt fence.