



2GC0259020100805

WOOD PARCEL NO D16-512-0203-01-029000 :2GC02590 2010/08/05 CLEMENT, SARAH PEMBERVILLE



**Environmental
Protection Agency**

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Korleski, Director

Re: Wood County
Parcel No D 16-512
Construction
Storm Water

August 5, 2010

Mr. Kurt Haar
2775 Sampson Road
Pemberville, Ohio 43450

Dear Mr. Haar:

On July 12, 2010, Judson Delancey and I inspected Parcel No D16-512-0203-01-029000 at 0 East Front Street in Pemberville, Ohio. The purpose of our visit was to evaluate compliance of the site with the National Pollutant Discharge Elimination System (NPDES) permit for storm water discharges associated with construction activity, Facility ID No 2 GC02590*AG. The inspection was conducted under the provisions of Ohio's water pollution control statutes, Ohio Revised Code (ORC) Chapter 6111.

As a result of the inspection, I have the following comments:

1. At the time of the inspection, the site was active. There was a backhoe and a dozer was working onsite. The part of the site, approximately half of the parcel, closest to East Front Street had been cleared of vegetation and grubbed. The back half of the parcel remained as a wooded area. There were stock piles on the west side of the site, just south of East Front Street.
2. Due to the absence of personnel, the Storm Water Pollution Prevention Plan (SWP3) and inspection logs were not available for review.
3. The stock piles on the west side of the site, just south of East Front Street, had no temporary stabilization established. As construction activity continues please keep in mind the permit requirements about temporary and permanent stabilization. *Permit Requires:* Portions of the construction site which will remain inactive for more than 21 day must have temporary stabilization initiated within the first seven. Permanent stabilization is required within seven days on any portion of the site that has reached final grade or will be idle for longer than one year. Permanent seeding and mulching is required before construction activity is completed throughout the entire site.

Mr. Kurt Haar
August 5, 2010
Page 2

If seasonal conditions prohibit the establishment of vegetative cover, other means, such as matting or mulching, must still be used and maintained until more permanent methods can be implemented. *Please see Part III.G.2.g.i. of the permit.*

4. Protection has not yet been provided on the south side of the property to keep sediment from being discharged into the low land/wetland area of the property. *This is a violation of Part III.G.2.f of the permit.*

Please send written notification of what corrective measures you have taken within 10 days of the date on this letter. Your response should include dates, either actual or purposed, for the completion of the actions.

If there are any questions, please contact me at (419) 373-3025.

Sincerely,



Sarah Clement
Division of Surface Water
Storm Water Program

/lr

pc: (DSW-NWDO File
Marcy Abke, Utility Clerk, Village of Pemberville
Raymond A. Huber, P.E., P.S., Wood County Engineer
Wood County SWCD