



State of Ohio Environmental Protection Agency

**Northwest District Office**

347 North Dunbridge Road  
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

Re: Richland County  
Rocky's Truck and Trailer Service  
NPDES Permit

June 2, 2008

Mrs. Shelly Fisher  
M&D Real Estate Investments  
2045 Millsboro Road  
Mansfield, Ohio 44906

Dear Mrs. Fisher:

On May 1, 2008, an inspection was made of the wastewater treatment facilities serving Rocky's Truck and Trailer Service located at 4732 U.S. 30, Springfield Township, Richland County. At the time of the inspection all major components of the treatment system appeared to be operating normally. No major concerns were noted.

Our office has been made aware that McGhee's Technical Water Service is the new operator of the treatment system. At the time of the inspection it was noted that the color of the water in the chlorine contact tank appeared almost black. The water in this tank may need to be pumped out and returned through the treatment plant. While empty, it should be verified that no solids have settled in the bottom of the chlorine tank.

Our office has received your discharge monitoring reports (DMRs) for the months of October 2007, through April 2008. A review of the data submitted shows several violations of the limits contained in your NPDES permit. A printout of these violations is included for your records. If solids are present in the chlorine tank, their decomposition could be adding to the violations.

If you have any questions please call me at 419-373-3070.

Sincerely,

  
Walter Ariss  
Environmental Specialist II  
Division of Surface Water

/llr

pc: DSW-NWDO  
Richland County Health Department  
Lonnie McGhee, McGhee's Technical Water Service Inc.

OHIO ENVIRONMENTAL PROTECTION AGENCY

OPERATION AND MAINTENANCE INSPECTION  
 WWTP'S LESS THAN 25,000 GPD

NPDES Permit No. 2PR00225

Facility Name Rocky's Trailer Trailer (M&D) Expiration Date 6/30/2011  
*Estate*

Facility Address 4732 Lincoln Highway Date 5/1/08 Time 10:00 am

City Crestline County Richland Township \_\_\_\_\_

Name and Address of Owner M&D Real Estate

Person Contacted \_\_\_\_\_ Owner Phone \_\_\_\_\_

Flow: Design 2,000 GPD Present 2400 GPD (metered - estimated)

Trib. Pop. \_\_\_\_\_ (actual - estimated) Weather at time of inspection: Temp 70° Sunny

OEPA Personnel Walter Ariss District NWDO

1. Plant Effluent - Mark Severity No.

No.	Severity Description	No.	Turbidity	No.	Odor	No.	Color
0	None	<input checked="" type="checkbox"/>	Clear	<input checked="" type="checkbox"/>	None	<input checked="" type="checkbox"/>	Colorless
1	Mild						
2	Moderate		Light Solids		Musty		Grey
3	Serious						
4	Extreme		Heavy Solids		Septic		Black

2. Effect of effluent on Receiving Stream Name: unsewered trib Paramour Creek - not observed

No.	Severity Description	No.	Turbidity	No.	Odor	No.	Color
0	None		Clear		None		Colorless
1	Mild						
2	Moderate		Light Solids		Musty		Grey
3	Serious						
4	Extreme		Heavy Solids		Septic		Black

3. a. Plant has \_\_\_\_\_ excellent  good \_\_\_\_\_ fair \_\_\_\_\_ poor operation  
 b. Plant has \_\_\_\_\_ excellent  good \_\_\_\_\_ fair \_\_\_\_\_ poor maintenance  
 c. Sand filters have \_\_\_\_\_ excellent  good \_\_\_\_\_ fair \_\_\_\_\_ poor maintenance

d. Not operating at expected efficiency due to:

- (1) \_\_\_\_\_ hydraulic overload  
 (2) \_\_\_\_\_ organic/ solids overload  
 (3) \_\_\_\_\_ personnel inefficiency  
 (4) \_\_\_\_\_ equipment failure  
 (5) \_\_\_\_\_ wastes  
 (6) \_\_\_\_\_

Disinfection: (Required May 1 thru Oct.31.)	
IN	OUT
<input checked="" type="checkbox"/>	_____ Chlorination Tablets
<input checked="" type="checkbox"/>	_____ Dechlorination Tablets
_____	_____ U.V.

Yes No

4.  Compliance with NPDES Permit

Periodic Violations Y N Parameters: NH3, TSS, BOD

Chronic Violations \_\_\_\_\_

5.  Adequate plant safety

6.  Operation and Maintenance Service Name McGhee's TWSF

Frequency of Visits ?

Facility Name: Rocky's Transfer (M&D real estate)

Process	# Units	Unit	If Needed - Description and Comments
Preliminary	<input checked="" type="checkbox"/>	Trash Trap	Pumping Frequency: ?
		Grease Trap	Pumping Frequency:
		Bar Screen	
		Comminutor	
		Flow Equalization	
Aeration Equipment	<input checked="" type="checkbox"/>	Plant Timer <u>Y</u> <del>Z</del> N Motor/ Blower Unit <i>running</i>	<del>Cycle time</del> <i>have a backup blower</i>
Secondary Treatment	<input checked="" type="checkbox"/>	Aeration Tank	Color: <i>good color / heavy billowing white foam</i> Adequate Aeration: <u>Y</u> <del>N</del>
Final Settling	<input checked="" type="checkbox"/>	Clarifier	<i>fairly turbid</i>
	<input checked="" type="checkbox"/>	Sludge Return	In <u>Y</u> Out <u>    </u>
	<input checked="" type="checkbox"/>	Surface Skimmer	In <u>    </u> Out <u>Y</u>
		Fixed Media Clarifier	
Tertiary Treatment	<input checked="" type="checkbox"/>	Surface Sand Filter	<i>Filter beds both clear</i>
		Polishing Pond	
		Other	
Disinfection	<input checked="" type="checkbox"/>	Chlorine Tube Feeder	<i>in</i>
	<input checked="" type="checkbox"/>	Dechlorination Tube Feeder	<i>in</i>
		Ultraviolet (UV)	
Flow Metering	<input checked="" type="checkbox"/>	Elapsed Pump Time	<i>on dosing station</i>
		Recorder (continuous total)	
Pumps		Raw Wastewater (type)	
	<input checked="" type="checkbox"/>	Sand Filter Effluent Dosing	<i>okay</i>
Sludge Handling		Aerated Storage Tank	
		Sludge Drying Bed	
Sludge Disposal	<input checked="" type="checkbox"/>	Municipal POTW	
		Landfill	
		Land Application	
Advanced Treatment		Post Aeration	
		Spray Irrigation	
		Other	