



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 16, 2010

RE: STARK COUNTY
BETHLEHEM TOWNSHIP
BETH MHP
6000 BETH AVENUE
NPDES #3PV00115

Mr. Robert Miller
Beth Mobile Home Park
6000 Beth Avenue SW
Canton, OH 44706

Dear Mr. Miller:

On March 11, 2010 a compliance evaluation inspection (CEI) was conducted by this writer of the wastewater treatment system serving the above referenced facility.

At the time of the inspection, the mixed liquor in the aeration tank had a light brown color. The final clarifier was producing a clear effluent. The surface sand filter was in good condition and the treatment system was producing a clear effluent that appeared to be of satisfactory quality. Noted was that the required sign was present at your final discharge.

A review of your Discharge Monitoring Reports (DMRs) covering the period November 2008 through January 2010 revealed the following effluent violations:

Numeric Violations

| Station | Parameter | Limit Type | Limit | Reported Value | Violation Date |
|---------|-------------------------|------------|-------|----------------|----------------|
| uu l | Nitrogen, Ammonia (NH3) | 30D Conc | 3.0 | 3.47 | 1/1/2009 |
| 001 | Total Suspended Solids | 30D Conc | 12 | 14. | 6/1/2009 |

Overall, the results of the inspection were satisfactory. Should you have any questions or comments regarding this letter, please contact this office at (330) 963-1136.

Sincerely,

Philip P. Rhodes, P.E.
Environmental Specialist II
Division of Surface Water

PPR/mt

cc: Todd Ascani, Stark County Health Department

File: Semi-Public/Beth Mobile Home Park