



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

January 15, 2010

RE: TOP O HILL MOBILE HOME PARK
4287 MANCHESTER RD.
3PV00099*BD
LAWRENCE TOWNSHIP
STARK COUNTY

Mr. Jacob Grimm
6408 South Main Street
Clinton, Ohio 44216

Dear Mr. Grimm:

On January 14, 2009 this writer conducted a compliance evaluation inspection at Top O Hill MHP. The following observations were made:

- The plant appeared to be in good operating condition.
- The clarifier was covered with a tarp to keep the surface from freezing due to the recent cold weather.
- The west half of the surface sand filter was in use. It must not be level as the flow during the inspection was observed as only covering half of the filter. The dose should cover the entire filter if it was level. Please instruct your operator to keep the filter sand surface level.
- The discharge was observed to be visually clear at the time of the inspection.

Pictures of the plant were taken for documentation. A review of your compliance with the limitations contained in your NPDES permit 3PV00099*BD, as identified by SWIMS, for the time period of November 2008 through December 2009 revealed the following violations:

Numeric Violations

Station	Reporting Code	Parameter	Limit Type	Limit	Reported Value	Violation Date
001	80082	CBOD 5 day	7D Conc	10	12.	2/1/2009
001	80082	CBOD 5 day	7D Qty	0.34	.44057	2/1/2009

If you should have any questions, feel free to contact this writer at (330) 963-1136.

Sincerely,

Philip P. Rhodes, P.E.
Environmental Specialist II
Division of Surface Water

PPR/mt

File: Semi-Public\Top O Hill MHP