



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

March 12, 2008

RE: SUMMIT COUNTY
FRANKLIN TOWNSHIP
REX HILL MOBILE ESTATES
COMPLIANCE EVALUATION INSPECTION
NPDES NO. OHOO98442
OHIO EPA NO. 3PV00049*DD

Mr. Jess Belton Jr., Owner
14961 Oak Grove Drive
Doylestown, OH 44230

Dear Mr. Belton:

On March 10, 2008, a compliance evaluation inspection was conducted at the wastewater treatment plant serving Rex Hill Mobile Estates. The plant consists of a 3735 gallon trash trap, a 765 gallon trash trap, a 30,000 gpd extended aeration treatment plant, a 1500 gallon dosing station, a 2500 square foot surface sand filter, chlorination/dechlorination, a 3000 gallon aerated sludge storage tank, and a 468 square foot sludge drying bed. The plant discharges to an unnamed tributary to the Tuscarawas River.

Due to the extreme amount of snow that day, a complete inspection couldn't be conducted. However, it was noted that the plant was running.

Upon reviewing your Monthly Operating Reports from January 2006 to January 2008, the following effluent violations were observed: CBOD violation in June and a fecal coliform violation in July.

In conclusion, the plant appears to be producing a good effluent. If you have any questions, please contact this office at (330) 963-1151.

Sincerely,

Jennifer S. Bennage
Environmental Engineer
Division of Surface Water

JSB/mt

cc: Richard Jackson, Certified Operator
Tom LaPlante, Summit County Health Dept.