

**Environmental
Protection Agency**

**Governor
Lt. Governor
Director**

August 10, 2011

RE: SUMMIT COUNTY
COPLEY TOWNSHIP
COVENANT OF GRACE CHURCH
3400 COPLEY ROAD
COMPLIANCE EVALUATION INSPECTION
OHIO EPA NO. 3PR00309

Covenant of Grace Church
Attn: Pastor Jim Walters
3400 Copley Road
Copley, OH 44321

Dear Pastor Walters:

On August 9, 2011, a Compliance Evaluation Inspection was conducted at the wastewater treatment plant serving Covenant of Grace Church. According to our files, the wastewater treatment system consists of a 500 gallon trash trap, 1500 gpd extended aeration plant, 500 gallon dosing chamber, 200 square foot surface sand filter, and 345 gallon chlorination/dechlorination tank. The plant discharges into a storm sewer along Copley Road and eventually enters Pigeon Creek.

During the inspection, the plant was running, and the effluent in the disinfection tank appeared clear of visible solids. The surface sand filter could use some weeding.

Upon review of your Discharge Monitoring Reports (DMRs) from August 2009 to August 2011, there were no numeric effluent violations and no monitoring violations. It was noticed that the flow rate for every single day was 100 gpd. How are you or your wastewater operator estimating this flow?

In conclusion, the plant appeared to be in satisfactory condition. If you have any questions concerning this letter, please contact this office at (330) 963-1151.

Sincerely,



Jennifer S. Bennage
Environmental Engineer
Division of Surface Water

JSB:bo

pc: Summit County Health Department