



State of Ohio Environmental Protection Agency

Southwest District Office

401 E. Fifth St.
Dayton, Ohio 45402

TELE: (937) 285-6357 FAX: (937) 285-6249
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

May 14, 2009

Robert Miller
10117 Old 3-C Highway
P.O. Box 157
Clarksville, Ohio 45113

RE: Joy Outdoor Education Center/Reconnaissance Inspection and Notice of
Violation, NPDES Permit No. OH0105392/ OEPA Permit No. 1PZ00045*AD

Mr. Miller:

On April 16, 2009, I conducted an NPDES Reconnaissance Inspection at the Joy Outdoor Education Center, during which you were present. The purpose of the inspection was to evaluate compliance with the terms and condition of the facility's NPDES permit.

Most areas that were evaluated received a satisfactory rating. The Records/Reporting section received a "Marginal" rating due to frequency violations over the past year of operations and the Effluent/Receiving Waters section received a "Marginal" due to monitoring violations over the past year. A copy of the inspection report is enclosed.

During the inspection you indicated that the chlorination system had broken and you will be using a floating pool chlorinator instead of replacing the system. This type of chlorinator is not designed to be used in a wastewater treatment system and actually releases much more chlorine than your original system, which can cause problems with the dechlorination system and lead to violations. Therefore you must replace the pool chlorinator with one designed to be used in a wastewater system within 30 days and notify this office when the repair has been made. Be aware that if you choose to install a chlorination system which is different from the original design, it will require a Permit to Install from this office before the work may proceed.

If you have any questions, please contact me by phone at (937) 285-6028 or by e-mail at michelle.waller@epa.state.oh.us.

Respectfully,

Michelle Waller
Environmental Specialist II
Division of Surface Water

Enclosures



State of Ohio Environmental Protection Agency
Southwest District Office

NPDES Compliance Inspection Report

Section A: National Data System Coding					
Permit #	NPDES#	Month/Day/Year	Inspection Type	Inspector	Facility Type
1PZ000045*AD	OH0105392	4/16/2009	R	S	2

Section B: Facility Data		
Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Joy Outdoor Education Center 10117 Old 3-C Highway Clarksville, Ohio 45113	2:00PM	3/1/2007
	Exit Time	Permit Expiration Date
	2:50PM	2/29/2012
Name(s) and Title(s) of On-Site Representatives	Phone Number(s)	
Robert Miller – Facility Director, Class A Operator	(937)-289-2031 ext. 223	
Name, Address and Title of Responsible Official	Phone Number	
Robert Miller 10117 Old 3-C Highway P.O. Box 157 Clarksville, Ohio 45113	(937)-289-2031 ext. 223	

Section C: Areas Evaluated During Inspection					
(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)					
S	Permit	S	Flow Measurement	S	Pretreatment
M	Records/Reports	N/E	Laboratory	N/A	Compliance Schedule
S	Operations & Maintenance	M	Effluent/Receiving Waters	S	Self-Monitoring Program
S	Facility Site Review	S	Sludge Storage/Disposal	S	Other
N/E	Collection System				

Section D: Summary of Findings (Attach additional sheets if necessary)	
See attached letter.	
Inspector	Reviewer
<i>Michelle Waller</i> 3/14/09	<i>Martyn Burt</i> 5/14/09
Michelle Waller Division of Surface Water Southwest District Office	Martyn Burt Compliance & Enforcement Supervisor Division of Surface Water Southwest District Office