

**Environmental  
Protection Agency**

John E. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott C. Nally, Director

October 17, 2011

RE: STARK COUNTY  
CANTON  
ENVIRITE  
OHIO EPA NO. 3IN00367\*AD

Ken Nisly  
Envirite  
2050 Central Avenue SE  
Canton, Ohio 44707

Dear Mr. Nisly:

On September 22, 2011, this writer conducted a Compliance Evaluation Inspection of your facility for the purpose of determining compliance with the above referenced National Pollutant Discharge Elimination System (NPDES) permit. Below is a summary of my observations:

- 1) The stairs down to outfall 001 have not been constructed as of yet.
- 2) Minor amounts of residuals were observed on the ground in and around the waste containers.
- 3) A very small amount of "leachate" was observed beneath one of the containers on the pad tributary to outfall 002.
- 4) In general there were quite a few waste containers that were not tarped, exposing residuals to precipitation. The containers, unless lined, are not leak proof. Therefore the potential to discharge "leachate" to the storm sewer system exists.

If you should have any questions, feel free to contact this writer at (330)963-1136 or by e-mail at [phil.rhodes@epa.state.oh.us](mailto:phil.rhodes@epa.state.oh.us).

Sincerely,



Philip P. Rhodes, P.E.  
Environmental Specialist II  
Division of Surface Water

PR/cs

File: Industrial permit/Compliance