



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korfeski, Director

April 2, 2008

Re: Adams County
Plum Run Quarry, Hanson Aggregates
Compliance Inspection
NPDES Permit 0IJ00012
Correspondence (IWW)

Ms. Mary Thompson Woodley, Env. Manager
Hanson Aggregates
1136 Morgantown Road
Russellville, KY 42276

Dear Ms. Thompson Woodley:

On March 27, 2008, Jack Knapp and I, representing Ohio EPA's Southeast District Office, performed a compliance inspection of the surface water and storm water discharge water treatment system associated with the Hanson Aggregates Plum Run operation. Steve Slack accompanied us and represented Hanson Aggregates during the inspection. The purpose of the inspection was to determine if the surface water and storm water treatment system was meeting the terms and conditions set forth in its NPDES permit.

The following concerns/comments arose during the inspection:

1. The process wash water settling pond appeared to have accumulated a significant amount of sediment during operation. The accumulated sediment appeared to be reducing the hydraulic capacity of the pond and subsequently reducing the treatment capacity of the pond. We recommend Hanson Aggregates dredge the accumulated sediment from the pond to restore the appropriate treatment capacity.

I have enclosed a copy of the inspection report. Should you have any questions, please feel free to contact me at (740) 380-5226.

Sincerely,


Patrick Hudnall
District Engineer
Division of Surface Water

PH/dh

Enclosure

c: Terry Louderback, Superintendent, Hanson Aggregates

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0IJ00012	OH0005151	March 27, 2008	C	S	2

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Plum Run Quarry 848 Plum Run Road Peeble, Ohio 45660	2:00 p.m.	July 1, 2003
	Exit Time	Permit Expiration Date
	2:30 p.m.	June 30, 2008

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Steve Slack, Plant Manager	(937) 364-2311
Name, Address and Title of Responsible Official	Phone Number
Hanson Aggregates 1136 Morgantown Road Russellville, KY 42276	(270) 726-4936


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>N/A</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>N/A</u> Compliance Schedules
<u>M</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>N/A</u> Sludge Storage/Disposal	<u> </u> Other
<u>N/A</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached inspection letter.



 Patrick Hudnall, Inspector, Ohio EPA, Southeast District Office

4/2/08

 Date



 Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

4/2/08

 Date