



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

April 28, 2008

Re: Athens County
Athens Hocking Reclamation Center
NPDES Permit 0IN00056
Compliance Inspection
Correspondence (IWW)

Mr. Edward F. Kilbarger, President
Athens Hocking Reclamation Center
Kilbarger Construction, Inc.
P.O. Box 946
Logan, Ohio 43138

Dear Mr. Kilbarger:

On April 16, 2008, I performed a compliance inspection of the storm water pollution prevention measures serving the Athens Hocking Reclamation Center located at 17970 State Route 33, Logan, Ohio. Bill Nye, representing the Athens Hocking Reclamation Center, assisted me during the inspection. The purpose of the inspection was to determine if Athens Hocking Reclamation Center is complying with the terms and conditions set forth in the NPDES Permit.

The following concerns arose during the inspection:

1. At the time of the inspection, the berm along the outside of the main haul road, adjacent to the unnamed tributary to the Hocking River, was breached in several locations to allow storm water runoff from the haul road to flow to the unnamed trib. The breaches in the haul road berm did not provide any type of sediment control prior to discharging the storm water runoff to the unnamed trib. In order to comply with the NPDES Permit, some type of sediment control must be installed prior to discharge of the haul road storm water runoff to the unnamed trib. We recommend the installation of sediment traps at each of the discharges of haul road storm water runoff. Your storm water pollution prevention plan should be updated to reflect these changes.
2. The following is a table of the monthly operating report violations for this facility for the period from January 2007 to April 2008. In your response to this letter, please provide an explanation for each of the limit violations in this table.

| Reporting Period | Station | Parameter | Limit Type | Limit | Reported Value | Violation Date |
|------------------|---------|------------------------|------------|-------|----------------|----------------|
| May 2007 | 001 | Total Suspended Solids | 1D Conc | 45 | 113. | 5/1/2007 |
| | 001 | Total Suspended Solids | 30D Conc | 30 | 60. | 5/1/2007 |
| July 2007 | 002 | Total Suspended Solids | 30D Conc | 30 | 38. | 7/1/2007 |

Our records also indicate that monthly operating reports were not submitted for following reporting periods: September of 2007 (both outfall 001 and 002), October of 2007 (both outfall 001 and outfall 002) and February of 2008 (both outfall 001 and 002). Failure to submit monthly operating reports is a violation of Part III, Item 4 of your NPDES permit and subjects you to significant monetary penalties. Please submit the missing monthly operating reports immediately.

Enclosed is a copy of the Compliance Evaluation Inspection report. Please respond to the comments listed above, in writing, within thirty (30) days of receiving this letter. Should you have any questions, please feel free to contact me at (740) 380-5226.

Sincerely,



Patrick Hudnall
District Engineer
Division of Surface Water

PH/dh

Enclosure

c: Mark Ruoff
c: Bill Nye

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

| Permit No. | NPDES No. | Date | Inspection Type | Inspector | Facility Type |
|------------|-----------|----------------|-----------------|-----------|---------------|
| OIN00056 | OH0076449 | April 16, 2008 | C | S | 2 |

B. FACILITY DATA

| Name and Location of Facility Inspected | Entry Time | Permit Effective Date |
|--|------------|------------------------|
| Athens Hocking Reclamation Center 17970 State Route 33 Logan, Ohio 43138 | 1:30 PM | June 1, 2006 |
| | Exit Time | Permit Expiration Date |
| | 2:00 PM | May 31, 2011 |

| Name(s) and Title(s) of On-Site Representative(s) | Phone Number(s) |
|---|-----------------|
| Bill Nye | 740-385-6019 |
| Name, Address and Title of Responsible Official | Phone Number |
| Kilbarger Construction, Inc. P.O. Box 946 Logan, Ohio 43138 | 740-385-6019 |


C. AREAS EVALUATED DURING INSPECTION

| | | |
|-----------------------------------|------------------------------------|----------------------------------|
| <u>S</u> Permit | <u>S</u> Flow Measurement | <u>N</u> Pretreatment |
| <u>N</u> Records/Reports | <u>S</u> Laboratory | <u>N/A</u> Compliance Schedules |
| <u>M</u> Operations & Maintenance | <u>M</u> Effluent/Receiving Waters | <u>S</u> Self-Monitoring Program |
| <u>M</u> Facility Site Review | <u>N</u> Sludge Storage/Disposal | <u> </u> Other |
| <u>N/A</u> Collection System | | |

(S = Satisfactory; M = Marginal; U = Unsatisfactory; N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See attached inspection letter



 Patrick Hudnall, Inspector, Ohio EPA, Southeast District Office

4/28/08

 Date



 Timothy M Campbell, Reviewer, Ohio EPA, Southeast District Office

4/20/08

 Date