



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
[www.epa.state.oh.us](http://www.epa.state.oh.us)

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

June 4, 2009

**Re:** Tuscarawas County  
Marlite, Inc.  
Compliance Evaluation Inspection  
Correspondence (IWW)

Mr. John Loibl, Process Manager  
Marlite, Inc.  
P.O. Box 250  
Dover, Ohio 44622-0250

Dear Mr. Loibl:

On April 26, 2006 and May 19, 2009, I conducted compliance evaluation inspections at Marlite, Inc. The purpose of the inspections was to determine compliance with the terms and conditions of National Pollutant Discharge Elimination System (NPDES) Permit Number 01N00010\*FD and to prepare for your permit renewal. You were present during the evaluation.

Marlite processes medium density fiberboard for architectural panels, wood veneers, etc. for retail store displays and commercial interiors. These panels vary from functional to decorative scoring. Some of the products are painted on-site. In addition, Marlite also produces toilet partitions and doors. Lastly, Marlite markets fiberglass reinforced polyester panels as well as adhesives and sealants.

Non-contact cooling water from the water cooled compressors is discharged through outfall 001 approximately four times per year. Since 2002, Marlite has been using the two air cooled compressors. The humidifier which was located on-site has been eliminated and is currently being removed from the site. There is no longer a discharge from this unit to outfall 001.


There are two dust collectors located outside the building around outfall 001. Marlite has good housekeeping procedures in these areas to prevent storm water from becoming contaminated. The general storm water permit requires Marlite develop and implement a Storm Water Pollution Prevention Plan (SWP3). Marlite may be able to certify "No Exposure" at their facility. Information regarding the "No Exposure" certification can be found at [http://www.epa.state.oh.us/dsw/storm/ind\\_noexp\\_cert.html](http://www.epa.state.oh.us/dsw/storm/ind_noexp_cert.html).

Your NPDES permit expired on February 28, 2006. Ohio EPA received your renewal application on January 20, 2006. We are in the process of renewing your permit. Marlite should continue to comply with the expired permit until a renewal permit is issued. Marlite will have thirty (30) days to comment on the draft permit when it is public noticed.

Outfalls 002 and 003 are storm water outfalls for runoff from roof drains and parking lots. These two outfalls will be removed from the permit. However, Marlite should continue to maintain the spill containment pit.

On the day of the inspection, Marlite was found to be in compliance with the permit. A copy of our completed inspection report is enclosed. Please submit a written response to the aforementioned comments within **30 days** of receipt of this letter. The assistance and cooperation received during the inspection are appreciated. If you have any questions, please feel free to call me at (740) 380-5206.

Sincerely,



Jennifer M. Witte  
Chemical Engineer - Environmental Specialist II  
Division of Surface Water

JMW/dh

Enclosure

c: Tuscarawas County Health Department

**NPDES**  
Compliance Inspection Report

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
01N00010*FD	OH0004936	May 19, 2009	C	S	2

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Marlite, Inc. 202 Harger Street Dover, Ohio 44622	10:00 a.m.	March 1, 2001
	Exit Time	Permit Expiration Date
	12:00 p.m.	February 28, 2006

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
John Loibl, Process Manager	(330) 343-6621
Name, Address and Title of Responsible Official	Phone Number
John Popa, President Marlite, Inc. 202 Harger Street Dover, Ohio 44622	(330) 343-6621


**C. AREAS EVALUATED DURING INSPECTION**

<u>  </u> S Permit	<u>  </u> S Flow Measurement	<u>  </u> -- Pretreatment
<u>  </u> S Records/Reports	<u>  </u> -- Laboratory	<u>  </u> S Compliance Schedules
<u>  </u> S Operations & Maintenance	<u>  </u> S Effluent/Receiving Waters	<u>  </u> S Self-Monitoring Program
<u>  </u> S Facility Site Review	<u>  </u> -- Sludge Storage/Disposal	<u>  </u> -- Other
<u>  </u> -- Collection System		


(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS** (attach additional sheets if necessary)

See attached letter.

  
\_\_\_\_\_  
Jennifer M. Witte, Inspector, Ohio EPA, Southeast District Office

6/4/09  
\_\_\_\_\_  
Date

  
\_\_\_\_\_  
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

6/4/09  
\_\_\_\_\_  
Date

**NPDES**  
Compliance Inspection Report

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
01N00010*FD	OH0004936	April 26, 2006	C	S	2

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Marlite, Inc. 202 Harger Street Dover, Ohio 44622	9:00 a.m.	March 1, 2001
	Exit Time	Permit Expiration Date
	10:30 a.m.	February 28, 2006

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
John Loibl, Process Manager	(330) 343-6621
Name, Address and Title of Responsible Official	Phone Number
John Popa, President Marlite, Inc. 202 Harger Street Dover, Ohio 44622	(330) 343-6621


**C. AREAS EVALUATED DURING INSPECTION**

<u>S</u> Permit	<u>S</u> Flow Measurement	<u>--</u> Pretreatment
<u>S</u> Records/Reports	<u>--</u> Laboratory	<u>S</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>--</u> Sludge Storage/Disposal	<u>--</u> Other
<u>--</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS** (attach additional sheets if necessary)

See attached letter.

  
Jennifer M. Witte, Inspector, Ohio EPA, Southeast District Office

6/4/09  
Date

  
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

6/4/09  
Date