



State of Ohio Environmental Protection Agency

**Southeast District Office**

2195 Front Street  
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

September 19, 2008

**Re:** Monroe County  
Village of Beallsville  
CEI 2009  
0PA00000\*HD  
Correspondence (PWW)

Mr. David Boyce  
Village of Beallsville WWTP  
P.O. Drawer E  
Beallsville, Ohio 43716

Dear Mr. Boyce:

On August 13, 2008, I conducted a Compliance Evaluation Inspection for your facility. The purpose of the inspection was to check the village's compliance status with its NPDES permit. I was accompanied by you. The following are comments from the inspection:

- Test Equipment Calibration
- Flow Meter Calibration
- The Collection System

**Test Equipment Calibration:**

The test equipment should be calibrated daily and before each use. The calibration records should be recorded in a log book or on a bench sheet and kept in a notebook. These are requirements contained in Part III, item 3 (A) of your NPDES permit.

**Flow Meter Calibration:**


The flow meter had not been calibrated for a few years and should be calibrated at least yearly. Regular maintenance should be provided to all equipment in the plant. You should consult the manufacturers specifications for calibration frequencies. Without proper calibration, this could lead to erroneous readings being reported on your monthly DMR. This is required by Part III, item 3(A) of your NPDES permit.

**The Collection System:**

Progress has been made in the collection system. A sewer study has been completed and the next phase of initiating repairs is ongoing.

A copy of the inspection report is attached. If you have any questions or comments, please feel free to call me at (740) 380-5227.

Sincerely,

A handwritten signature in black ink, appearing to read "Scott Foster", with a long horizontal flourish extending to the right.

Scott Foster  
Environmental Specialist 2  
Division of Surface Water

SF/dh

Enclosure

c: John Gramlich, Mayor

**NPDES**  
Compliance Inspection Report

**A. NATIONAL DATA SYSTEM CODING**

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
0PA00000*HD	OH0020885	August 13, 2008	C	S	1

**B. FACILITY DATA**

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Village of Beallsville WWTP County Road 1 Kings Highway Beallsville, Ohio 43716	9:55 a.m.	April 1, 2008
	Exit Time	Permit Expiration Date
	10:35 a.m.	March 31, 2013

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
David Boyce, Operator	(740) 926-9181
Name, Address and Title of Responsible Official	Phone Number
John Gramlich, Mayor Village of Beallsville P.O. Drawer E Beallsville, Ohio 43716	(740) 926-9177


**C. AREAS EVALUATED DURING INSPECTION**

<u>  </u> S Permit	<u>  </u> M Flow Measurement	<u>  </u> N Pretreatment
<u>  </u> S Records/Reports	<u>  </u> S Laboratory	<u>  </u> N Compliance Schedules
<u>  </u> S Operations & Maintenance	<u>  </u> S Effluent/Receiving Waters	<u>  </u> S Self-Monitoring Program
<u>  </u> S Facility Site Review	<u>  </u> S Sludge Storage/Disposal	<u>  </u> N Other
<u>  </u> M Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

**D. SUMMARY OF FINDINGS/COMMENTS** (attach additional sheets if necessary)

See attached letter.

  
\_\_\_\_\_  
Scott Foster, Inspector, Ohio EPA, Southeast District Office

9/19/08  
\_\_\_\_\_  
Date

  
\_\_\_\_\_  
Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

9/19/08  
\_\_\_\_\_  
Date