



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

December 22, 2009

Re: Morgan
Burr Oak Campground and Beach
2010 CEI
Correspondence (PWW)

Mr. Eric Compston, Operator
Burr Oak Campground and Beach
10660 Burr Oak Lodge Road
Glouster, Ohio 45732

Dear Mr. Compston:

On October 20, 2009, I conducted a Compliance Evaluation Inspection at Burr Oak Campground and Beach located in Glouster, Ohio. Cynthia Yandrich, with this office, assisted me with the inspection. You and other ODNR personnel represented Burr Oak and accompanied me during the inspection. The purpose of the inspection was to determine Burr Oak's compliance with NPDES Permit Number 0PP00044*DD and the Ohio Water Pollution Control Act, Revised Code Chapter 6111.

As a result of the inspection and review of our files, I have the following comments:


1. There were NPDES permit violations in December of 2008. Ohio EPA never received a written response to address the violations. In accordance with Part III, Item 12 of your NPDES permit, Burr Oak is required to submit a written response.
2. The effluent flow meter was out of calibration. In accordance with Part III, Item 3 of your NPDES permit, Burr Oak is required to maintain and operate their treatment facility as efficiently as possible. The effluent flow meter had not been calibrated in the last calendar year. The meter should be calibrated immediately and at least annually thereafter.
3. The collection system in the campground has major I/I issues. The I/I problems must be resolved to comply with Part III, Item 3 of the permit. In your response to this letter, please provide a detailed plan to address this problem.

Attached is a copy of the inspection report which indicates marginal and/or unsatisfactory evaluations of the following areas: Collection System, Operations and Maintenance, Facility Site Review, Flow Measurement. I gave these ratings because of

the deficiencies mentioned in the above comments. Burr Oak should take the appropriate actions to return the facility to compliance with all terms and conditions of the NPDES permit.

The Ohio EPA strongly encourages pollution prevention as the preferred approach for waste management. The first priority of pollution prevention is to eliminate the generation of wastes and pollutants at the source (source reduction). For those wastes or pollutants that are generated, the second priority is to recycle or reuse them in an environmentally sound manner. You can benefit economically, help preserve the environment, and improve your public image by implementing pollution prevention programs. For more information about pollution prevention, including fact sheets and U.S. EPA's Facility Pollution Prevention Guide, (EPA/600/R-92/088), you may contact the Ohio EPA Pollution Prevention Section at (614) 644-3469 or me for additional information.

Sincerely,



Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

- c: Mike Powers, Park Manager
- c: Greg Masterson, Treatment Plant Manager

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

| Permit No. | NPDES No. | Date | Inspection Type | Inspector | Facility Type |
|-------------|-----------|------------------|-----------------|-----------|---------------|
| OPP00044*DD | OH0048330 | October 20, 2009 | C | S | 1 |

B. FACILITY DATA

| Name and Location of Facility Inspected | Entry Time | Permit Effective Date |
|---|------------|------------------------|
| Ohio Department of Natural Resources Burr Oak State Park, Campground and Beach WWTP County Road 107 Glouster, Ohio 45732 | 3:10 p.m. | March 1, 2007 |
| | Exit Time | Permit Expiration Date |
| | 3:40 p.m. | February 29, 2012 |

| Name(s) and Title(s) of On-Site Representative(s) | Phone Number(s) |
|--|-----------------|
| Eric Compston, Operator | (740) 767-4915 |
| Name, Address and Title of Responsible Official | Phone Number |
| Mike Powers, Park Manager 10660 Burr Oak Lodge Road Glouster, Ohio 45732 | (740) 767-3570 |

C. AREAS EVALUATED DURING INSPECTION

| | | |
|-----------------------------------|------------------------------------|----------------------------------|
| <u>S</u> Permit | <u>U</u> Flow Measurement | <u>N/A</u> Pretreatment |
| <u>S</u> Records/Reports | <u>S</u> Laboratory | <u>N/A</u> Compliance Schedules |
| <u>M</u> Operations & Maintenance | <u>S</u> Effluent/Receiving Waters | <u>S</u> Self-Monitoring Program |
| <u>M</u> Facility Site Review | <u>S</u> Sludge Storage/Disposal | <u>N/A</u> Other |
| <u>U</u> Collection System | | |

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)

See attached letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

12/22/09

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

12/23/09

Date